



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS3/SMO22007917/TEcy3m4 Date: 11/10/2022 Code: SMO	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	GBH 4978L	Veh. Inspected	SLV 7564K	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2202833/AGC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	18/08/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA CITY	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MRHGM6660JT000297	Colour	BLUE	
Odometer	66912 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	185/55 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	185/55 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	185/55 R16	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION & UNDERCARRIAGE.				
<b>5. General Information</b>				
Accident Date	12/08/2022	Inspection Date	22/08/2022	
Survey held at	PROWERKZ GARAGE PTE LTD 25 KAKI BUKIT RD 4 #06-87 SYNERGY @ KB SINGAPORE 417800			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	