

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TF 3082/08/22

Your Ref: _____

Date: 18th AUGUST 2022

MR TAN CHEE TONG
BLK 231, #02-1240
ANG MO KIO AVE 3
SINGAPORE 560231

not Allowed
Her
2/5 \$2000
Hdms

23/8/22

Estimate cost of repair to KIA CERATO 1.6 (A) EX-Saloon - SMM 8855 A

- 1 pc rear n/s door
- 1 set rear n/s door frame black sticker
- 18 pcs rear n/s door inner trim board clips
- 1 pc n/s rocker panel sideskirt
- 10 pcs n/s rocker panel sideskirt clips
- 1 pc rear n/s sport rim
- 1 pc rear bumper
- 1 pc rear bumper n/s side retainer
- 10 pcs rear bumper clips
- 6 pcs rear n/s fender inner garnish clips

	2	\$ 1,138.00	X
	11	27.00	X
@ \$ 6.00	11	108.00	X
	CM	685.00	
@ \$ 6.50	11	65.00	
	2	585.00	X
	2	688.00	X
	11	28.00	X
@ \$ 3.50	11	35.00	
@ \$ 6.50	11	39.00	X
		\$ 3,398.00	
Less 20%		\$ 679.60	
		\$ 2,718.40	

50.00 20

To wiring check up for affected wiring system.

To remove & refix rear n/s door inner trim board cover, glass, inner lock, glass regulator, channel, weatherstrip moulding, handle & necessary parts.

11 150.00

To remove & refix cushion seat, carpet, floor mat, garnish & necessary parts, to enable repair rear n/s fender & necessary parts.

11 120.00

120.00 60

To check & adjust wheel alignment & balancing.

120.00 60

To remove, refix & pump sealant for rocker panel sideskirt.

11 90.00

To respray Tuff-Kote on all affected accident parts.

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear n/s fender & necessary parts, to weld, renew & align above parts.

950.00

To putty & respray painting on all affected accident parts.

1,250.00

\$ 5,568.40

Dollars : Five Thousand Five Hundred Sixty Eight And Cents Forty Only.

HUP MOTOR TRADING & SERVICE

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s), during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-785
202
628
1890
2518