

Date: 18/08/2022
 Vehicle No: SJZ1212T
 Model: SKODA OCTAVIA ESTATE 2.0 VRS
 Chassis: TMBKU8NX3MY192930
 Reg.Year: 2021

Third Party Insurer: AIG
 Third Party Veh No: SHD9808L
 Date of Accident: 17/08/2022
 Estimator: Victor
 Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER / Re	1		\$2,750.00
2	FRONT GRILLE ASSY / C.A.	1		\$575.00
3	BONNET / Bmc.	1		\$3,550.00
4	FRONT EMBLEM / nbc.	1		\$155.00
5	REAR BUMPER / Re.	1		\$2,750.00
6	REAR LOWER BUMPER / Re.	1		\$800.00
7	TAILGATE / Bmc.	1		\$5,100.00
8	REAR LOCK ?	1		\$240.00
9	REAR LOCK STRIKER ?	1		\$130.00
10	REAR END PANEL INNER ?	1		\$1,100.00
11	REAR END PANEL OUTER ?	1		\$800.00
12	REAR REINFORCEMENT ?	1		\$650.00
13	END PANEL TOP COVER ?	1		\$240.00
14	REAR SKODA EMBLEM /	1		\$165.00
15	REAR VRS EMBLEM / } nbc.	1		\$185.00
16	REAR OCTAVIA EMBLEM /	1		\$185.00
17	REAR WEATHERSTRIP ?	1		\$260.00
18	REAR SENSORS ?	2	\$220.00	\$440.00
19	FRONT SENSORS ?	2	\$220.00	\$440.00
SUB TOTAL				\$20,515.00
LESS 10%				-\$2,051.50
PARTS TOTAL				\$18,463.50

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT / nbc.	1		\$80.00
3	REAR NUMBER PLATE WITH HOLDER	1		\$75.00
4	REAR BUMPER CLIPS / nbc.	1		\$80.00
6	REAR END PANEL JOINT SEALANT ?	1		\$80.00
7	REAR END PANEL TOP GARNISH CLIPS ?	1		\$30.00
8	FRONT NUMBER PLATE WITH HOLDER / nbc.	1		\$75.00
9	FRONT GRILLE CLIPS /	1		\$50.00
10	FRONT BUMPER CLIPS / } nbc.	1		\$80.00
S/N TOTAL				\$550.00

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 18/08/2022
Vehicle No: SJZ1212T
Model: SKODA OCTAVIA ESTATE 2.0 VRS
Chassis: TMBKU8NX3MY192930
Reg.Year: 2021

Third Party Insurer: AIG
Third Party Veh No: SHD9808L
Date of Accident: 17/08/2022
Estimator: Victor
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST FRONT ACCIDENT AREA.	\$700.00	400
LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT FRONT ACCIDENT AREA.	\$800.00	400
LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST REAR ACCIDENT AREA.	\$800.00	400
LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT REAR ACCIDENT AREA.	\$1,200.00	600
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS.	\$120.00	—
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM BACK TO ORIGINAL OPERATIONS.	\$120.00	60
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR.	\$100.00	40
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$150.00	?
TO DIAGNOSIS FAULT CODE & RESET MEMORY.	\$120.00	?
TO CHECK WIRING & ELECTRICAL DIAGNOSTIC	\$80.00	30

LABOUR TOTAL \$4,190.00

TOTAL \$23,203.50

6 Days.
Complete repair
After repair photos
Gina Qian
8-88 or 82
19/8/22

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: