

Vehicle Damage Assessment Report for [GBJ190H]

Estimate Created: 17/08/2022 04:06 by Sharon_Ow (JP_Knight)

Owned: 17/08/2022 09:39 by Sharon_Ow (JP_Knight)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	JP_Knight	Reference Number

Vehicle Information

Brand	Kia	Model	K-Series
Engine Type			
License Plate Number	GBJ190H	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Recommended cost of repair at the range of \$1000.00 to \$1140.00 with 4 days for repair Insurlogic 1 (17/08/2022 09:39)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRONT BUMPER		1	180.00	10.00 %	198.00
HEADLAMP RH		1	280.00	10.00 %	308.00
Parts Subtotal					506.00

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
COMPANY INFO STICKER		1.0	35.00	0.00 %	35.00
Materials Subtotal					35.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
REPLACE FRONT BUMPER AND HEADLAMP RH	RnR	200.00	0.00 %	200.00

Repair

Description	Severity	Cost	Markup/Disc %	Price
REPAIR FRONT CORNER PANEL AND FRONT DOOR RH	Unknown	150.00	0.00 %	150.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
FRONT DOOR AND FRONT CORNER PANEL RH	Full spray	250.00	0.00 %	250.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 350.00

Paint Labor Subtotal 250.00

Labor Subtotal 600.00

Summary

Repair Cost	1,141.00
Discount(0 %)	(0.00)
	1,141.00
Excess	(0.00)
GST(0.00 %)	0.00

Grand Subtotal	1,141.00
----------------	----------