


ASS. REC'D BY: Toupin

REF: 04/1112700793/1/T 993

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / IS / TP RES / OD RES / EVA / INV / MV
 To Inspect/ehicle No: _____
 at Works/tp m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SK826584 Yr Regn: 2016 Jan
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Axio C.C. 1426
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 99787 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: NRE/6100/1435
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 185/64R15
 R: 27



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 946K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS WP
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 18/8/22
 Survey held at Bijvoort
 Des. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? : Prel. Report
 : Final Report
 1) _____
 Date/Time, File Return to?

Days Of Repair: _____
 Resurvey No. of Trip: _____

2) _____
 Report Format: _____
 Lump Sum / I.B.I. (P) _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. rvs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____
 S + RS \$ _____
 Photos _____
 Others _____
 TOTAL _____

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875
Tel: 93290237 Email: claims_rar@bifrostauto.com

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : **SKZ 2658Y**
Made : Toyota
Model : Corolla Axio 1.5X
Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear Bootlid	1	\$ 947.50	\$ <i>bt</i> 947.50
2	Rear Bootlid Insulator	1	\$ 168.30	\$ <i>X</i> 168.30
3	Rear Bootlid Hinge RH	1	\$ 125.80	\$ <i>Ry</i> 125.80
4	Rear Bootlid Hinge LH	1	\$ 125.80	\$ <i>KY</i> 125.80
5	Rear Bootlid Lock	1	\$ 108.60	\$ <i>blc</i> 108.60
6	Rear Bootlid Lock Catch	1	\$ 94.30	\$ <i>x</i> 94.30
7	Rear Bootlid Emblem	1	\$ 63.80	\$ <i>nel</i> 63.80
8	Rear Bootlid "Axio" Emblem	1	\$ 48.60	\$ <i>nel</i> 48.60
9	Rear Bootlid "Corolla" Emblem	1	\$ 42.70	\$ <i>nel</i> 42.70
10	Rear Bootlid Weatherstrip	1	\$ 185.20	\$ <i>cut</i> 185.20
11	Rear Bootlid Outer Chrome Garnish	1	\$ 312.80	\$ <i>cong</i> 312.80
12	Rear Bootlid Key Lock	1	\$ 95.80	\$ <i>X</i> 95.80
13	Rear Bootlid Number Plate Lamp RH	1	\$ 75.10	\$ <i>X</i> 75.10
14	Rear Bootlid Number Plate Lamp LH	1	\$ 75.10	\$ <i>X</i> 75.10
15	Rear Bumper	1	\$ 1,249.60	\$ <i>del</i> 1,249.60
16	Rear Bumper Reflector RH	1	\$ 58.60	\$ <i>cut</i> 58.60
17	Rear Bumper Reflector LH	1	\$ 58.60	\$ <i>X</i> 58.60
18	Rear Bumper Side Retainer RH	1	\$ 95.80	\$ <i>del</i> 95.80
19	Rear Bumper Side Retainer LH	1	\$ 95.80	\$ <i>X</i> 95.80
20	Rear Bumper Bracket RH	1	\$ 75.60	\$ <i>X</i> 75.60
21	Rear Bumper Bracket LH	1	\$ 75.60	\$ <i>X</i> 75.60
22	Rear Taillamp Assembly RH	1	\$ 548.70	\$ <i>cong</i> 548.70
23	Rear Taillamp Assembly LH	1	\$ 548.70	\$ <i>cong</i> 548.70
24	Rear Taillamp Lower Bracket RH	1	\$ 58.60	\$ <i>cong</i> 58.60
25	Rear Taillamp Lower Bracket LH	1	\$ 58.60	\$ <i>cong</i> 58.60
26	Rear Taillamp Panel RH	1	\$ 325.10	\$ <i>del</i> 325.10
27	Rear Taillamp Panel LH	1	\$ 325.10	\$ <i>X</i> 325.10
28	Rear Fender RH	1	\$ 876.70	\$ <i>del</i> 876.70
29	Rear Fender LH	1	\$ 876.70	\$ <i>X</i> 876.70
30	Rear Fender Inner Cowling RH	1	\$ 58.60	\$ <i>X</i> 58.60
31	Rear Fender Inner Cowling LH	1	\$ 58.60	\$ <i>X</i> 58.60
32	Rear Fender Inner Trim RH	1	\$ 319.90	\$ <i>m</i> 319.90

33	Rear Fender Inner Trim LH	1	\$	319.90	\$ 319.90	319.90
34	Rear Fender Air Vent RH	1	\$	128.60	\$ X	128.60
35	Rear Fender Air Vent LH	1	\$	128.60	\$ X	128.60
36	Rear Windscreen Glass Moulding	1	\$	89.60	\$ X	89.60
37	Rear End Panel	1	\$	602.10	\$ 602.10	602.10
38	Rear End Panel Top Garnish	1	\$	226.20	\$ 226.20	226.20
39	Rear Spare Tyre Panel	1	\$	702.95	\$ 702.95	702.95
40	Rear Spare Tyre Panel Top Board	1	\$	461.90	\$ 461.90	461.90
41	Rear Spare Tyre Panel Tools Sponge	1	\$	378.30	\$ X	378.30
42	Rear Exhaust Pipe	1	\$	902.10	\$ X	902.10
43	Rear Exhaust Insulator	1	\$	245.70	\$ X	245.70
44	Rear Exhaust Mounting	2	\$	45.10	\$ X	90.20
45	Rear Exhaust Gasket	1	\$	38.90	\$ X	38.90
Parts Sub Total :					\$	12,549.35
25% Discount					\$	3,137.34
PARTS TOTAL :					\$	9,412.01

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear Number Plate	1	\$ 50.00	\$ X 50.00
2	Rear Bumper Clips - Set	1	\$ 50.00	\$ 50.00 50.00
3	Rear Bootlid Inner Trim Clips - Set	1	\$ 50.00	\$ X 50.00
4	Rear Bootlid Outer Chrome Garnish Clips - Set	1	\$ 30.00	\$ X 30.00
5	Rear End Panel Top Garnish Clips - Set	1	\$ 50.00	\$ 50.00 50.00
6	Rear Fender Inner Trim Clips RH - Set	1	\$ 50.00	\$ X 50.00
7	Rear Fender Inner Trim Clips LH - Set	1	\$ 50.00	\$ X 50.00
8	Rear Fender Inner Cowling Clips RH - Set	1	\$ 50.00	\$ X 50.00
9	Rear Fender Inner Cowling Clips LH - Set	1	\$ 50.00	\$ X 50.00
10	Rear Bootlid Sealant	1	\$ 150.00	\$ X 150.00
11	Rear End Panel Sealant	1	\$ 150.00	\$ 150.00 150.00
12	Rear Fender RH Sealant	1	\$ 150.00	\$ X 150.00
13	Rear Fender LH Sealant	1	\$ 150.00	\$ X 150.00
14	Rear Spare Tyre Panel Sealant	1	\$ 150.00	\$ X 150.00
15	Rear Windscreen Glass Sealant	1	\$ 150.00	\$ X 150.00
16	Rear Bumper Reverse Sensor - Set	1	\$ 250.00	\$ 250.00 250.00
17	Rear Bootlid Reverse Camera	1	\$ 550.00	\$ 550.00 550.00
SPECIAL NETT TOTAL :				\$ 2,130.00

Nos.	LABOUR	TOTAL S\$
1	To Panel Beat, Remove & Refix Parts	\$ 2400 2,400.00
2	To Spray Paint Affected Areas	\$ 1600 1,600.00
3	Wiring & Bulb Check	\$ 30 100.00
4	To Transfer Rear Bootlid Mechanism	\$ 60 150.00
5	To Remove & Refix Rear Windscreen Glass	\$ X 150.00
6	To Remove & Refix Rear Bumper Reverse Sensor	\$ 30 120.00
7	To Remove & Refix Rear Bootlid Reverse Camera	\$ 30 150.00

8	To Remove & Refix Rear Exhaust Pipe to facilitate repairs	\$ X	150.00
9	To Remove & Refix Fuel Tank to facilitate repairs	\$ X	250.00
10	To apply anti rust on affected parts	\$ 50	180.00
11	To Remove & Refix Interior Upholstry to facilitate repairs	\$ 60	150.00
12	To Conduct Water Leak Test	\$ X	100.00
13	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ X	480.00
LABOUR TOTAL :		\$	5,980.00

PARTS TOTAL : \$ 9,412.01
 SPECIAL NETT TOTAL : \$ 2,130.00
 LABOUR TOTAL : \$ 5,980.00
GRAND TOTAL : \$ 17,522.01

Taufik 97495749
 WP 18/8/22 @ 945
 L/S Resurvey after repair
 Taufik @ Thando van
 7 days

To check consistency of accident
 To check part price.

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 563I

Vehicle Details

Vehicle No.: SKZ2658Y
Vehicle to be Exported: Yes
Intended Deregistration Date: 17 Aug 2022
Vehicle Make: TOYOTA
Vehicle Model: COROLLA AXIO 1.5X CVT ABS D/AIRBAG 2WD
Primary Colour: Silver
Manufacturing Year: 2015
Engine No.: 2NR8528138
Chassis No.: NRE1610011435
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$14,416.00
Original Registration Date: 15 Jan 2016
First Registration Date: 15 Jan 2016
Transfer Count: 0
Actual ARF Paid: \$9,416.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 14 Jan 2026
PARF Rebate Amount: \$6,120.00

Intended COE Rebate Details

COE Expiry Date: 14 Jan 2026
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$55,399.00
COE Rebate Amount: \$18,883.00
Total Rebate Amount: \$25,003.00

The information contained herein is correct as at 17 Aug 2022

OK