



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0711/2022/EQ  
DATE : 18-Aug-22  
WIP : 37951

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/08/2022

**AIG ASIA PACIFIC INSURANCE PTE LTD**  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
Attn: Motor Claims Dept  
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR HENG CHENG HUA  
ADDRESS : 17 CAIRNHILL CIRCLE  
#09-08  
SINGAPORE 229816  
TELEPHONE : HP +65 97832466  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 2100503266-05  
VEHICLE NO : **SLM 1828 L**  
MODEL CODE : Q7 2.0 TFSI  
MODEL YEAR : 10/3/2017  
ENGINE NO : CYR 025299  
CHASSIS NO : WAUZZZ4M1HD027689  
MILEAGE : 167209KM  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 18-Aug-22  
PLACE OF ACCIDENT : NUL ROAD, SLIP ROAD TO KAMPONG BAHRU ROAD



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLM 1828 L**

| S/N                         | NATURE OF JOBS   | ESTIMATED CHARGES        | SURVEYOR'S RECOMMENDATIONS   |
|-----------------------------|--|--------------------------|--|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.                                 | S/N \$ 480.00            | ✓  |
| 2                           | TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.  | S/N \$ <del>450.00</del> | 300  |
| 3                           | TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.   | S/N \$ 280.00            | X  |
| 4                           | TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO REPAIR RHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$ <del>3,600.00</del>   | 1200.  |
| 5                           | TO RESPRAY FRONT BUMPER, <del>RHS FRONT BUMPER</del> LOWER SPOILER, BONNET, RHS FRONT FENDER, RHS FRONT DOOR, DOOR COVER AND BOTH FRONT WHEEL ARCH TRIMS.                        | \$ <del>6,000.00</del>   | Bumper : 600<br>Lower Spoiler : 300<br>Bonnet 600<br>Wheel Arch X2 = 400<br>Door Cover : 250 |
| <b>TOTAL LABOUR CHARGES</b> |  | <b>\$ 10,810.00</b>      | <u>2150</u>  |

2450

~~6,000.00~~

1200.

Bumper : 600  
 Lower Spoiler : 300  
 Bonnet 600  
 Wheel Arch X2 = 400  
 Door Cover : 250

2150



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLM 1828 L**

| S/N                         | NATURE OF JOBS  |          | ESTIMATED CHARGES   | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|---|----------|---------------------|----------------------------|
| 6                           | TO CARRY OUT CALIBRATION FOR FRONT BUMPER RADAR SENSOR AND DISTANCE REGULATION. | S/N S    | 480.00              | ✓                          |
| 7                           | TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.   | S/N S    | <del>384.00</del>   | 192 .                      |
| <b>TOTAL LABOUR CHARGES</b> |   | <b>:</b> | <b>\$ 11,674.00</b> |                            |

COB



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLM 1828 L**

|                              |  |          | DAMAGED PARTS & PRICES |         |
|------------------------------|--|----------|------------------------|---------|
| S/N                          | PARTS DESCRIPTION                                      | QTY      | S/NETT                 | REMARKS |
| 1                            | FRONT BUMPER <i>Defend</i>                             | 1        | \$ 2,896.00            | ✓       |
| 2                            | FRONT BUMPER FIXING PARTS <i>? New</i>                 | 1        | \$ 468.00              | X       |
| 3                            | FRONT BUMPER TOW EYE COVER                             | 1        | \$ 44.00               | X       |
| 4                            | FRONT BUMPER AIR GUIDE - RH <i>?</i>                   | 1        | \$ 75.00               | ?       |
| 5                            | FRONT BUMPER END CAP - RH <i>?</i>                     | 1        | \$ 40.00               | ?       |
| 6                            | FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE <i>New</i> | 1        | \$ 309.00              | X       |
| 7                            | FRONT BUMPER GRILLE- LOWER CENTRE <i>New</i>           | 1        | \$ 230.00              | X       |
| 8                            | FRONT BUMPER UNDERRUN BAR - LOWER <i>New</i>           | 1        | \$ 899.00              | X       |
| 9                            | FRONT BUMPER CLOSING ELEMENT                           | 1        | \$ 235.00              |         |
| 10                           | FRONT BUMPER SPOILER - RH <i>could</i>                 | 1        | \$ 235.00              | ✓       |
| 11                           | FRONT BUMPER OUTER SPOILER - RH <i>?</i>               | 1        | \$ 49.00               | ?       |
| 12                           | RADIATOR GRILLE <i>? New</i>                           | 1        | \$ 2,741.00            | X       |
| 13                           | RADIATOR GRILLE COVER                                  | 1        | \$ 81.00               | X       |
| 14                           | FRONT BUMPER INNER COVER <i>?</i>                      | 1        | \$ 69.00               | ?       |
| 15                           | FRONT AIR GUIDE GRILLE - RH <i>Defend</i>              | 1        | \$ 332.00              | ✓       |
| 16                           | FRONT AIR GUIDE GRILLE END CAP - RH <i>?</i>           | 1        | \$ 38.00               | ?       |
| 17                           | FRONT INNER SPOILER - RH <i>?</i>                      | 1        | \$ 65.00               | ?       |
| 18                           | FRONT BUMPER FOAM FILLER PIECE <i>?</i>                | 1        | \$ 192.00              | ?       |
| 19                           | FRONT BUMPER CARRIER <i>?</i>                          | 1        | \$ 1,025.00            | ?       |
| 20                           | FRONT BUMPER GUIDE SECTION - RH <i>?</i>               | 1        | \$ 50.00               | ?       |
| <b>SUB TOTAL SPARE PARTS</b> |  | <b>:</b> | <b>\$ 10,073.00</b>    |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLM 1828 L**

| S/N                          | PARTS DESCRIPTION                                 | QTY      | DAMAGED PARTS & PRICES |         |
|------------------------------|---|----------|------------------------|---------|
|                              |   |          | S/NETT                 | REMARKS |
| 21                           | FRONT BUMPER SENSOR SUPPORT - LH / RH <i>RH?</i>  | 2        | \$ 81.00               | ?       |
| 22                           | FRONT BUMPER TOP COVER <i>?</i>                   | 1        | \$ 146.00              | X       |
| 23                           | CAUTION SIGN STICKER <i>?</i>                     | 1        | \$ 16.00               | X       |
| 24                           | AIR CONDITIONER STICKER <i>?</i>                  | 1        | \$ 9.00                | X       |
| 25                           | HORN HIGH TONE - RH <i>?</i>                      | 1        | \$ 240.00              | X       |
| 26                           | FRONT PARKING AID SENSOR - INNER / OUTER <i>?</i> | 2        | \$ 531.00              | X       |
| 27                           | FRONT PARKING AID SEAL RING <i>?</i>              | 4        | \$ 10.00               | X       |
| 28                           | FRONT FENDER - RH <i>Repair</i>                   | 1        | \$ 1,819.00            | X       |
| 29                           | FRONT FENDER ATTACHMENT PARTS <i>?</i>            | 1        | \$ 79.00               | X       |
| 30                           | FRONT FENDER BRACE <i>?</i>                       | 1        | \$ 171.00              | ?       |
| 31                           | FRONT FENDER BRACKET - RH <i>?</i>                | 1        | \$ 72.00               | ?       |
| 32                           | FRONT WHEEL HOUSING LINER- RH <i>?</i>            | 1        | \$ 260.00              | X       |
| 33                           | WHEEL HOUSING LINER - RH REAR <i>?</i>            | 1        | \$ 260.00              | X       |
| 34                           | BONNET <i>Dented</i>                              | 1        | \$ 7,032.00            | ✓       |
| 35                           | BONNET IMPACT PROTECTION <i>?</i>                 | 1        | \$ 119.00              | ✓       |
| 36                           | BONNET STRICKER PLATE - RH <i>?</i>               | 1        | \$ 131.00              | X       |
| 37                           | BONNET LID LOCK - RH <i>?</i>                     | 1        | \$ 243.00              | X       |
| 38                           | HEADLIGHT TRIM COVER - RH <i>?</i>                | 1        | \$ 114.00              | ?       |
| 39                           | FRONT ENGINE HOOD TRIM COVER - RH <i>?</i>        | 1        | \$ 50.00               | X       |
| 40                           | HEADLIGHT MOUNTING - RH <i>?</i>                  | 1        | \$ 132.00              | ?       |
| <b>SUB TOTAL SPARE PARTS</b> |   | <b>:</b> | <b>\$ 11,515.00</b>    |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.





55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLM 1828 L**

|                             |   | DAMAGED PARTS & PRICES |                     |         |
|-----------------------------|---|------------------------|---------------------|---------|
| S/N                         | PARTS DESCRIPTION                           | QTY                    | S/NETT              | REMARKS |
| 41                          | HEADLIGHT <i>cracked.</i>                   | 1                      | \$ 10,660.00        | ✓       |
| 42                          | HEADLIGHT COOLING FAN - RH                  | 1                      | \$ 428.00           | X       |
| 43                          | HEADLIGHT POWER MODULE - RH                 | 1                      | \$ 842.00           | X       |
| 44                          | HEADLIGHT CONTROL UNIT - RH                 | 1                      | \$ 840.00           | X       |
| 45                          | HEADLIGHT VENT HOSE - RH                    | 1                      | \$ 45.00            | X       |
| 46                          | LIFT CYLINDER - RH ?                        | 1                      | \$ 217.00           | ?       |
| 47                          | LIFT CYLINDER HOSE <i>new</i>               | 1                      | \$ 113.00           | X       |
| 48                          | FRONT WHEEL COVER - LH } <i>new</i>         | 1                      | \$ 607.00           | ✓       |
| 49                          | FRONT WHEEL COVER - RH                      | 1                      | \$ 607.00           | ✓       |
| 50                          | FRONT DOOR COVER - RH <i>Repair</i>         | 1                      | \$ 734.00           | X       |
| 51                          | FRONT UNDERBODY NOISE INSULATION <i>new</i> | 1                      | \$ 725.00           | X       |
| 52                          | RADIATOR SUPPORT BAFFLE - RH ?              | 1                      | \$ 33.00            | ?       |
| 53                          | RADIATOR SUPPORT AIR DUCT - UPPER ?         | 1                      | \$ 48.00            | ?       |
| 54                          | RADIATOR SUPPORT AIR DUCT - LOWER ?         | 1                      | \$ 48.00            | ?       |
| 55                          | FRONT NO PLATE <i>new</i>                   | S/N                    | \$ 60.00            | X       |
| 56                          | SUNDRIES ?                                  |                        | \$ 500.00           | ?       |
| <b>TOTAL SPARE PARTS</b>    |   | :                      | <b>\$ 38,095.00</b> |         |
| <b>TOTAL LABOUR CHARGES</b> |   | :                      | <b>\$ 11,674.00</b> |         |
| <b>GRAND TOTAL</b>          |   | :                      | <b>\$ 49,769.00</b> |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

