

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0711/2022/EQ
29-Aug-22
CHANG
1 of 1
SLM 1828 L
AUDI Q7 2.0 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	\$ 1,800.00	✓✓
2	TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.	\$ 3,600.00	1800. ✓
Parts			
1	HORN BRACKET - RH Bent.	\$ 33.00	25.76
2	FRONT LOCK CARRIER cracked.	\$ 1,335.00	1068
3	COOLANT new	\$ 297.00	237.12
4	WIRE CONNECTOR 2mgd	\$ 68.00	54.40
GRAND TOTAL			\$ 7,133.00

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling
Resigned H's.
To add 3 days. For the
replacement of the lock carrier