



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0711/2022/EQ
DATE : 18-Aug-22
WIP : 37951

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/08/2022

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR HENG CHENG HUA
ADDRESS : 17 CAIRNHILL CIRCLE
#09-08
SINGAPORE 229816
TELEPHONE : HP +65 97832466
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100503266-05
VEHICLE NO : **SLM 1828 L**
MODEL CODE : Q7 2.0 TFSI
MODEL YEAR : 10/3/2017
ENGINE NO : CYR 025299
CHASSIS NO : WAUZZZ4M1HD027689
MILEAGE : 167209KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Aug-22
PLACE OF ACCIDENT : NUL ROAD, SLIP ROAD TO KAMPONG BAHRU ROAD



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLM 1828 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 450.00	300 ✓
3	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.	S/N \$ 280.00	X
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO REPAIR RHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,600.00	1200 ✓
5	TO RESPRAY FRONT BUMPER, RHS FRONT BUMPER LOWER SPOILER, BONNET, RHS FRONT FENDER, RHS FRONT DOOR, DOOR COVER AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 6,000.00	Bumper : 600 Lower Spoiler : 300 Bonnet 600 Wheel Arch X2 = 400 Door Cover : 250
TOTAL LABOUR CHARGES		\$ 10,810.00	2150 ✓

2450

~~3,600.00~~
E

~~6,000.00~~

1200 ✓

Bumper : 600
Lower Spoiler : 300
Bonnet 600
Wheel Arch X2 = 400
Door Cover : 250

2150 ✓



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLM 1828 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO CARRY OUT CALIBRATION FOR FRONT BUMPER RADAR SENSOR AND DISTANCE REGULATION.	S/N S	480.00	✓ ✓
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N S	384.00 192	✓
TOTAL LABOUR CHARGES		:	\$ 11,674.00	

COB



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLM 1828 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Defend</i>	1	\$ 2,896.00	✓ 2316.80
2	FRONT BUMPER FIXING PARTS <i>3 new</i>	1	\$ 468.00	X
3	FRONT BUMPER TOW EYE COVER <i>nec</i>	1	\$ 44.00	X 35.12
4	FRONT BUMPER AIR GUIDE - RH <i>? nn</i>	1	\$ 75.00	? X
5	FRONT BUMPER END CAP - RH <i>? nn</i>	1	\$ 40.00	? X
6	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE <i>HE m</i>	1	\$ 309.00	X
7	FRONT BUMPER GRILLE- LOWER CENTRE <i>HE m</i>	1	\$ 230.00	X
8	FRONT BUMPER UNDERRUN BAR - LOWER <i>HE m</i>	1	\$ 899.00	X 719.20
9	FRONT BUMPER CLOSING ELEMENT <i>nn</i>	1	\$ 235.00	X
10	FRONT BUMPER SPOILER - RH <i>could</i>	1	\$ 235.00	✓ 187.60
11	FRONT BUMPER OUTER SPOILER - RH <i>? nn</i>	1	\$ 49.00	? X
12	RADIATOR GRILLE <i>3 new</i>	1	\$ 2,741.00	X
13	RADIATOR GRILLE COVER <i>1</i>	1	\$ 81.00	X
14	FRONT BUMPER INNER COVER <i>? nn</i>	1	\$ 69.00	? X
15	FRONT AIR GUIDE GRILLE - RH <i>Defend</i>	1	\$ 332.00	✓ 265.60
16	FRONT AIR GUIDE GRILLE END CAP - RH <i>? nn</i>	1	\$ 38.00	? X
17	FRONT INNER SPOILER - RH <i>? nn</i>	1	\$ 65.00	? X
18	FRONT BUMPER FOAM FILLER PIECE <i>? cracked</i>	1	\$ 192.00	? 153.20
19	FRONT BUMPER CARRIER <i>? nn</i>	1	\$ 1,025.00	? X
20	FRONT BUMPER GUIDE SECTION - RH <i>? cracked</i>	1	\$ 50.00	? 39.52
SUB TOTAL SPARE PARTS		:	\$ 10,073.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLM 1828 L

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	FRONT BUMPER SENSOR SUPPORT - LH / RH <i>2 damaged</i>	2	\$ 81.00	? 32
22	FRONT BUMPER TOP COVER <i>? new</i>	1	\$ 146.00	X
23	CAUTION SIGN STICKER <i>? new</i>	1	\$ 16.00	X
24	AIR CONDITIONER STICKER <i>nec</i>	1	\$ 9.00	+ 6.64
25	HORN HIGH TONE - RH <i>new</i>	1	\$ 240.00	X
26	FRONT PARKING AID SENSOR - INNER / OUTER <i>new</i>	2	\$ 531.00	X
27	FRONT PARKING AID SEAL RING <i>new</i>	4	\$ 10.00	X
28	FRONT FENDER - RH <i>Repair</i>	1	\$ 1,819.00	X
29	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 79.00	X
30	FRONT FENDER BRACE <i>? bent</i>	1	\$ 171.00	? 136.80
31	FRONT FENDER BRACKET - RH <i>? nn</i>	1	\$ 72.00	? X
32	FRONT WHEEL HOUSING LINER - RH <i>? new</i>	1	\$ 260.00	X
33	WHEEL HOUSING LINER - RH REAR <i>? new</i>	1	\$ 260.00	X
34	BONNET <i>Dented</i>	1	\$ 7,032.00	✓ 5625.60
35	BONNET IMPACT PROTECTION <i>new</i>	1	\$ 119.00	✓ 95.20
36	BONNET STRICKER PLATE - RH <i>? new</i>	1	\$ 131.00	X
37	BONNET LID LOCK - RH	1	\$ 243.00	X
38	HEADLIGHT TRIM COVER - RH <i>? nn</i>	1	\$ 114.00	? X
39	FRONT ENGINE HOOD TRIM COVER - RH <i>new</i>	1	\$ 50.00	X
40	HEADLIGHT MOUNTING - RH <i>? cracked</i>	1	\$ 132.00	? 105.20
SUB TOTAL SPARE PARTS		:	\$ 11,515.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.





55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLM 1828 L

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
41	HEADLIGHT <i>cracked.</i>	1	\$	10,660.00	✓	8528
42	HEADLIGHT COOLING FAN - RH	1	\$	428.00	X	
43	HEADLIGHT POWER MODULE - RH	1	\$	842.00	X	
44	HEADLIGHT CONTROL UNIT - RH	1	\$	840.00	X	
45	HEADLIGHT VENT HOSE - RH	1	\$	45.00	X	
46	LIFT CYLINDER - RH <i>? cracked</i>	1	\$	217.00	?	173.60
47	LIFT CYLINDER HOSE <i>new</i>	1	\$	113.00	X	
48	FRONT WHEEL COVER - LH <i>? new</i>	1	\$	607.00	✓	485.60
49	FRONT WHEEL COVER - RH	1	\$	607.00	✓	485.60
50	FRONT DOOR COVER - RH <i>Repair</i>	1	\$	734.00	X	
51	FRONT UNDERBODY NOISE INSULATION <i>new</i>	1	\$	725.00	X	
52	RADIATOR SUPPORT BAFFLE - RH <i>? nn</i>	1	\$	33.00	?	X
53	RADIATOR SUPPORT AIR DUCT - UPPER <i>? nn</i>	1	\$	48.00	?	X
54	RADIATOR SUPPORT AIR DUCT - LOWER <i>? nn</i>	1	\$	48.00	?	X
55	FRONT NO PLATE <i>new</i>	S/N	\$	60.00	X	
56	SUNDRIES <i>? nn</i>		\$	500.00	?	X
TOTAL SPARE PARTS		:	\$	38,095.00		
TOTAL LABOUR CHARGES		:	\$	11,674.00		
GRAND TOTAL		:	\$	49,769.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

