



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0711/2022/EQ
DATE : 18-Aug-22
WIP : 37951

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/08/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

*Hi Adrian
10 days exclude 1 Sunday
Johnny Boo 11 Nov 22*

OWNER'S NAME : MR HENG CHENG HUA
ADDRESS : 17 CAIRNHILL CIRCLE
#09-08
SINGAPORE 229816
TELEPHONE : HP +65 97832466
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100503266-05
VEHICLE NO : **SLM 1828 L**
MODEL CODE : Q7 2.0 TFSI
MODEL YEAR : 10/3/2017
ENGINE NO : CYR 025299
CHASSIS NO : WAUZZZ4M1HD027689
MILEAGE : 167209KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Aug-22
PLACE OF ACCIDENT : NUL ROAD, SLIP ROAD TO KAMPONG BAHRU ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLM 1828 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	450.00	\$	300.00
3	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.	S/N \$	280.00		
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO REPAIR RHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	3,600.00	\$	1,200.00
5	TO RESPRAY FRONT BUMPER, RHS FRONT BUMPER LOWER SPOILER, BONNET, RHS FRONT FENDER, RHS FRONT DOOR, DOOR COVER AND BOTH FRONT WHEEL ARCH TRIMS.	\$	6,000.00	\$	2,150.00
TOTAL LABOUR CHARGES		:	\$ 10,810.00	\$	4,130.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLM 1828 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>C/F</i>		\$ 4,130.00
6	TO CARRY OUT CALIBRATION FOR FRONT BUMPER RADAR SENSOR AND DISTANCE REGULATION.	S/N \$	480.00	\$ 480.00
7	Added labour		\$ 5,400.00	\$ 3,600.00
8	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$	384.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 17,074.00	\$ 8,402.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLM 1828 L

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,896.00	\$	2,316.80
2	FRONT BUMPER FIXING PARTS	1	\$ 468.00		
3	FRONT BUMPER TOW EYE COVER	1	\$ 44.00	\$	35.12
4	FRONT BUMPER AIR GUIDE - RH	1	\$ 75.00		
5	FRONT BUMPER END CAP - RH	1	\$ 40.00		
6	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	1	\$ 309.00		
7	FRONT BUMPER GRILLE- LOWER CENTRE	1	\$ 230.00		
8	FRONT BUMPER UNDERRUN BAR - LOWER	1	\$ 899.00	\$	719.20
9	FRONT BUMPER CLOSING ELEMENT	1	\$ 235.00		
10	FRONT BUMPER SPOILER - RH	1	\$ 235.00	\$	187.60
11	FRONT BUMPER OUTER SPOILER - RH	1	\$ 49.00		
12	RADIATOR GRILLE	1	\$ 2,741.00		
13	RADIATOR GRILLE COVER	1	\$ 81.00		
14	FRONT BUMPER INNER COVER	1	\$ 69.00		
15	FRONT AIR GUIDE GRILLE - RH	1	\$ 332.00	\$	265.60
16	FRONT AIR GUIDE GRILLE END CAP - RH	1	\$ 38.00		
17	FRONT INNER SPOILER - RH	1	\$ 65.00		
18	FRONT BUMPER FOAM FILLER PIECE	1	\$ 192.00	\$	153.20
19	FRONT BUMPER CARRIER	1	\$ 1,025.00		
20	FRONT BUMPER GUIDE SECTION - RH	1	\$ 50.00	\$	39.52
SUB TOTAL SPARE PARTS			\$ 10,073.00	\$	3,717.04

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLM 1828 L

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	3,717.04
21	FRONT BUMPER SENSOR SUPPORT - LH / RH	2	\$	81.00	\$ 32.00
22	FRONT BUMPER TOP COVER	1	\$	146.00	
23	CAUTION SIGN STICKER	1	\$	16.00	
24	AIR CONDITIONER STICKER	1	\$	9.00	\$ 6.64
25	HORN HIGH TONE - RH	1	\$	240.00	
26	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$	531.00	
27	FRONT PARKING AID SEAL RING	4	\$	10.00	
28	FRONT FENDER - RH	1	\$	1,819.00	
29	FRONT FENDER ATTACHMENT PARTS	1	\$	79.00	
30	FRONT FENDER BRACE	1	\$	171.00	\$ 136.80
31	FRONT FENDER BRACKET - RH	1	\$	72.00	
32	FRONT WHEEL HOUSING LINER- RH	1	\$	260.00	
33	WHEEL HOUSING LINER - RH REAR	1	\$	260.00	
34	BONNET	1	\$	7,032.00	\$ 5,625.60
35	BONNET IMPACT PROTECTION	1	\$	119.00	\$ 95.20
36	BONNET STRICKER PLATE - RH	1	\$	131.00	
37	BONNET LID LOCK - RH	1	\$	243.00	
38	HEADLIGHT TRIM COVER - RH	1	\$	114.00	
39	FRONT ENGINE HOOD TRIM COVER - RH	1	\$	50.00	
40	HEADLIGHT MOUNTING - RH	1	\$	132.00	\$ 105.20
SUB TOTAL SPARE PARTS			:	\$ 11,515.00	\$ 9,718.48

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLM 1828 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 9,718.48
41	HEADLIGHT	1	\$ 10,660.00	\$ 8,528.00
42	HEADLIGHT COOLING FAN - RH	1	\$ 428.00	
43	HEADLIGHT POWER MODULE - RH	1	\$ 842.00	
44	HEADLIGHT CONTROL UNIT - RH	1	\$ 840.00	
45	HEADLIGHT VENT HOSE - RH	1	\$ 45.00	
46	LIFT CYLINDER - RH	1	\$ 217.00	\$ 173.60
47	LIFT CYLINDER HOSE	1	\$ 113.00	
48	FRONT WHEEL COVER - LH	1	\$ 607.00	\$ 485.60
49	FRONT WHEEL COVER - RH	1	\$ 607.00	\$ 485.60
50	FRONT DOOR COVER - RH	1	\$ 734.00	
51	FRONT UNDERBODY NOISE INSULATION	1	\$ 725.00	
52	RADIATOR SUPPORT BAFFLE - RH	1	\$ 33.00	
53	RADIATOR SUPPORT AIR DUCT - UPPER	1	\$ 48.00	
54	RADIATOR SUPPORT AIR DUCT - LOWER	1	\$ 48.00	
55	FRONT NO PLATE	S/N	\$ 60.00	
56	Added parts		\$ 1,733.00	\$ 1,385.28
57	SUNDRIES		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 39,828.00	\$ 20,776.56
TOTAL LABOUR CHARGES		:	\$ 17,074.00	\$ 8,402.00
GRAND TOTAL		:	\$ 56,902.00	\$ 29,178.56

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-14/10/22



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0711/2022/EQ 29-Aug-22 CHANG 1 of 1 SLM 1828 L AUDI Q7 2.0 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE AND RENEW AIRCON CONDENSER, S/N CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	\$ 1,800.00	\$ 1,800.00
2	TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.	\$ 3,600.00	\$ 1,800.00
		\$ 5,400.00	\$ 3,600.00
Parts			
1	HORN BRACKET - RH	\$ 33.00	\$ 25.76
2	FRONT LOCK CARRIER	\$ 1,335.00	\$ 1,068.00
3	COOLANT	\$ 297.00	\$ 237.12
4	WIRE CONNECTOR	\$ 68.00	\$ 54.40
	MATERIALS	\$ 1,733.00	\$ 1,385.28
	LABOUR	\$ 5,400.00	\$ 3,600.00
	GRAND TOTAL	\$ 19,666.00	\$ 4,985.28

For Premium Automobiles Pte Ltd

 Authorised Signature



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT