

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA1097P

Date: 18/08/2022

Make : HYUNDAI

Insurance: NTUC

Model : I-40

MVA: MS. LOKE Y Y

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER X Repair			\$ 553.00
1	REAR BUMPER CLIPS X			\$ 22.00
1	REAR BUMPER LOWER COVER X			\$ 228.00
1	REAR BUMPER REINFORCEMENT X			\$ 428.40
SUB TOTAL				\$ 1,231.40
LESS 20%				\$ 246.28
DISCOUNTED TOTAL				\$ 985.12
	REAR BUMPER REVERSE SENSOR X			\$ 135.70
				\$ 135.70
	Labour Charge			
	PANEL BEATING			\$ 300.00
	SPRAY PAINTING CHARGE			\$ 300.00
	REMOVE/REFIX REVERSE SENSOR			\$ 60.00
	TOTAL LABOUR			\$ 660.00
	ESTIMATE TOTAL			\$ 1,780.82

Nett
Nett

280
250
X

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

1 Day
4/5
Good King
3:23 pm
18/8/22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices correct until next repair
- Third party claims on "without prejudice" basis
- No illegal modifications
- Supply items to be replaced surveyed and is subject to the approval of the Insurance Company

Acknowledged by Repairer
Signature:
Date: