

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHD3648X

Make : HYUNDAI

Model : I-40

Date: 18/08/2022

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT DOOR LH <i>X Repair</i>			\$ 2,707.70
1	ROCKER COVER GARNISH LH <i>CRA</i>			\$ 732.80
SUB TOTAL				\$ 3,440.50
LESS 20%				\$ 688.10
DISCOUNTED TOTAL				\$ 2,752.40
	RR DOOR COMFORT APP LOGO LH <i>// 4342</i>	10%		\$ 80.00
	FRT DOOR COMFORT LOGO LH			\$ 75.00
				\$ 75.00
Labour Charge				
	PANEL BEATING			\$ 900.00
	SPRAY PAINTING CHARGE			\$ 1,000.00
	TRANSFER OF FRT DOOR			\$ 120.00
	TUFF KOTE			\$ 60.00
TOTAL LABOUR				\$ 2,080.00
ESTIMATE TOTAL				\$ 4,907.40

Nett

Nett

Nett

280

750

4987.40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2 days.
45
Gao Qus

3:30pm

18/8/22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts after resurvey
- Parts prices are on a "no prejudice" basis
- Third parties are on a "no prejudice" basis
- No illenation shall be involved
- Supplementary items must be surveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date: