

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CC3/AIS22007943/RNY3Q2**Date:** 26/09/2022**REFERENCE**

Insured/Claimant:	MANJA HABIB	Policy No:	SP2000423616-01	
Date of Loss:	12/08/2022	Nature of Claim:	OD	Claim No: 20222006115

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT7221Z		
Make & Model:	VOLKSWAGEN PASSAT CC, 1.8 TSI (A)	Engine No:	CJS308755
Reg. Date:	15/07/2020 (Man. Year: 2019)	Chassis No:	WVWZZZ3CZKE135542
Colour:	Black	Odometer:	44347 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$124,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,419.74	2,347.90	1,071.84	31.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,100.00	2,180.00	4,920.00	69.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,519.74	4,527.90	5,991.84	56.96
+ GST 7.00/7.00% (S\$)	736.38	316.95	419.43	56.96
Nett Amount (S\$)	11,256.12	4,844.85	6,411.27	56.96

INSPECTION

Date of Assignment:	15/08/2022		
Date Inspected:	19/08/2022	Inspected At:	Volkswagen Group Singapore Pte Ltd 247 ALEXANDRA ROAD Singapore 159934
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD RASUL**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Sep 2022)
Parts:	143	VOLKSWAGEN PASSAT CC 1.8 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMT7221Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*INSCRIPTION BRIGHT CHROME REAR BOOT LID NAME PLATE - PASSAT	Not Necessary	59.26 FS	*- FS
2	1		*COVER PRIMED REAR BUMPER	Cracked	1,293.72 FS	*1,293.72 FS
3	1		*SPOILER PRIMED	Cracked	273.49 FS	*273.49 FS
4	1		*SET SENSOR BRACKETS	Necessary	35.24 FS	*35.24 FS
5	1		*2K-PLASTIC ADHESIVE	Necessary	61.88 FS	*61.88 FS
6	1		*BONDING AGENT FOR PLASTIC	Necessary	49.57 FS	*49.57 FS
7	1		*POP-RIVET (10 PCS)	Necessary	9.79 FS	*9.79 FS
8	1		*BUMPER REINFORCEMENT	Not Necessary	637.23 FS	*- FS
9	1		*ATTACHMENT STRIP BUMPER CTR BRACKET	Not Necessary	51.81 FS	*- FS
10	1		*GUIDE LHR BUMPER BRACKET (UPPER)	Not Necessary	20.15 FS	*- FS
11	1		*GUIDE RHR BUMPER BRACKET (UPPER)	Not Necessary	20.15 FS	*- FS
12	1		*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	Not Necessary	34.39 FS	*- FS
13	1		*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	Not Necessary	34.39 FS	*- FS
14	1		*DECORATIVE MOULDING BRIGHT BUMPER LOWER MLDG CHROM (CTR)	Cut	172.16 FS	*172.16 FS
15	1		*DECORATIVE MOULDING BRIGH BUMPER LOWER MLDG CHROM (RH)	Cracked	132.36 FS	*132.36 FS
16	1		*REFLECTOR RHS REFLECTOR INNER	Cracked	54.57 FS	*54.57 FS
17	1		*REFLECTOR RHS REFLECTOR OUTER	Cracked	54.57 FS	*54.57 FS
18	1		*ACOUSTIC UNDERBODY TRIM REAR BUMPER LOWER COVER	Deformed	205.80 FS	*205.80 FS
19	1		*RIVET (5 PCS)	Necessary	4.75 FS	*4.75 FS
20	1		*WHEELHOUSE PROTECTOR RHS REAR FENDER LINER	Not Necessary	196.68 FS	*- FS
21	1		*BOLT FOR SPARE WHEEL MOUN SPARE WHEEL BOLT	Not Necessary	17.78 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **3,419.74** **2,347.90**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT/ HARNESS REPAIR	New	200.00	200.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	360.00	360.00
3	LABOUR	New	3,360.00	560.00
4	SPRAY PAINT	New	3,180.00	1,060.00
Gross Labour Cost (\$\$)			7,100.00	2,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >