

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 24 Aug 2022

Preliminary Advice

Vehicle No	: SCK6911M	Accident Date	: 16/08/2022
Make	: TOYOTA HARRIER	Policy No.	: SP2001218400-001
Assignment Date	: 19/08/2022	Excess	: S\$0.00
Date of Inspection	: 23/08/2022	Est. Duration of Repair	: 5
Inspection At	: KT MOTORWERK (HQ) BLK 3012 BEDOK INDUSTRIAL PARK E, #01-2020 SINGAPORE 489978		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,536.28
Revised Amount	:S\$	6,755.03
Check Items (Estimated)	:S\$	6,314.08
Total	:S\$	13,069.11

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	110,000.00
COE / PARF Rebate	:S\$	47,052.00
Salvage Value	:S\$	
Margin for Repair	:S\$	62,948.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :lump sum repair.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.