



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22007951/Aqy3m4 Date: 24/03/2023	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGL 1898Z	Veh. Inspected	SLR 8256P	
Policy No.	P10363788R01	Coverage (\$)	0.00	
Claim No.	C10017030/JT	Excess (\$)	0.00	
Assign From	SALIZAWATI HAIZAR	Assign Date	19/08/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HARRIER	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTEZB3GH50J000161	Colour	BLACK	
Odometer	107645 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/55 R18	BRIDGESTONE	6 mm	
L/H Front Tyre	235/55 R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	235/55 R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	235/55 R18	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/08/2022	Inspection Date	22/08/2022	
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		