

ASS. REC. BY:

REF:

Tm1 / 22007952/Kgc

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

17/8 21/8 842501. Carw used to 28348. 73, 87/10

Date/Time, File Pass to?

1) 23/9 2022

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) 4250

mer to

4250

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

Site Insp (\$)

Interview (\$)

Tech Invs (\$)

Weekend (\$)

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 878K

Vehicle Details

Vehicle No.: SHD317X

Vehicle to be Exported: Yes

Intended Deregistration Date: 15 Aug 2022

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2015

Engine No.: M9R8839C002972

Chassis No.: VF1ABL15AUC282370

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 04 Mar 2016

First Registration Date: 04 Mar 2016

Transfer Count: 0

Actual ARF Paid: \$19,998.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 03 Mar 2024

PARF Rebate Amount: \$12,998.00

Intended COE Rebate Details

COE Expiry Date: 03 Mar 2024

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$39,633.00

COE Rebate Amount: \$7,670.00

Total Rebate Amount: \$20,668.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 15 Aug 2022

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD317X*Not Notified*
*11 Aug @ 4250h***AAD2208-070**

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

16 AUG 2022**SHD317X**

VF1ABL15AUC282370

200303878K

RENAULT

LATITUDE

12/08/2022

GBJ5412K/ *Tokio*

04/03/2016

PART		LIST	
1	FENDER PANEL REAR RH	\$	<i>n</i> 1,933.20 X
1	WHEELARCH REAR RH	\$	<i>sn</i> 275.40 X
1	BONNET	\$	<i>n</i> 1,312.70 X
1	BONNET HINGE LH	\$	<i>n</i> 237.40 X
1	BONNET HINGE RH	\$	<i>n</i> 237.40 X
1	HEADLAMP RH	\$	<i>sn</i> 743.60 X
1	ROCKER PANEL OUTER RH	\$	<i>n</i> 1,184.99 X
1	DOOR MIRROR RH	\$	<i>Not/um</i> 1,483.40 ✓
1	FENDER PANEL FRT RH	\$	<i>Ry</i> 437.10 ✓
1	WHEELARCH FRT RH	\$	<i>sn</i> 191.40 X
1	BUMPER COVER FRT	\$	<i>sn</i> 747.20 X
1	BUMPER BRACKET KIT FRT RH	\$	<i>sn</i> 101.40 X
1	DOOR PANEL FRT RH	\$	<i>Ry</i> 2,844.66 ✓
		\$	11,729.85
		10% \$	1,172.99
		\$	10,556.87

Specical Nett			
1	FENDER CLIP	\$	<i>nn</i> 120.00 X
1	FENDER LINER CLIP	\$	<i>nn</i> 130.00 X
1	FRT BUMPER CLIP	\$	<i>nn</i> 65.00 X
1	RIM	\$	<i>sn</i> 350.00 X
1	DOOR STICKER TRANSCAB	\$	<i>nn</i> 100.00 <i>65.00</i>
2	WINDSCREEN SEALANT	\$	<i>nn</i> 150.00 X
1	WINDSCREEN MOULDING	\$	<i>nn</i> 200.00 X
1	WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 130.00 X
	TOTAL	\$	1,245.00

Trans-cab Auto Services Pte Ltd

AAD2208-070

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD317X

TOTAL PARTS	\$	11,801.87
-------------	----	-----------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	500
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	400
To Rust-Proofing Of The Affected Areas.	\$	170.00	60
To reinstall rear bumper parking sensor.	\$	170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X
To repair and realign rear exhaust pipe.	\$	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20

TOTAL	\$	10,240.00
-------	----	-----------

Over All Total	\$	32,598.73
----------------	----	-----------

(LUMP SUM)

Repair Days

20 DAYS

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: