

ASS. REC. BY:

REF:

Sma 2200 7961/K943

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1) 31/8/22

Date/Time, File Return to?

2)

☐ : Prell. Report☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

) S + RS SI

) Fuel


) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

2600



29/8 61Ry @ 2600 Cash 30/8/22
(Red, \$ 2681.72, 51%)

EM Solution Pte Ltd

160 Sin Ming Drive #03-18/19, Sin Ming Autocity

Singapore 575722

Tel: 64560226 Fax: 64584500

GST Reg. No: 201016308K

*NOT Authorized
C1 Rep & 2600hr
Penny After Pairs
4 delays*

ESTIMATE

Date : 22nd August 2022

M/s **Cai Yi Service**
Blk 120D Canberra Crescent
#10-407 Eastwave@Canberra
Singapore 754120

Veh No : **SMQ 695B**
Make/Model : **Honda Vezel**
Chassis No : RU11317608
Date of Acc : 18.08.22
TP Veh No : SKW 4967H

S/No	Qty	Description	Unit Price	Amount
Materials				
1	1 pc	Rear Tailgate <i>953</i>	\$ <i>B</i> 1,240.90	✓
2	1 pc	Rear Tailgate Honda Logo	\$ <i>nn</i> 35.00	X
3	1 pc	Rear Tailgate Vezel Emblem	\$ <i>nn</i> 66.20	✓
4	1 pc	Rear Bumper <i>762.70</i>	\$ <i>B</i> 983.50	✓
5	1 pc	Rear Bumper Side Holder LH	\$ <i>B</i> 42.00	X
6	1 pc	Rear Bumper Reflector LH	\$ <i>cm</i> 42.00	✓
7	1 pc	Rear End Panel	\$ <i>R</i> 630.00	X
8	1 pc	Rear End Panel Top Garnish	\$ <i>B</i> 102.00	X
9	1 pc	Rear Boot Weatherstrip	\$ <i>B</i> 105.70	X
10	1 pc	Rear Windscreen Moulding <i>110</i>	\$ <i>nn</i> 140.00	✓
			\$ 3,387.30	
Less 20% :			\$ 677.46	
			\$ 2,709.84	
Special Nett				
1	1 set	Rear Bumper Clips	\$ <i>nn</i> 45.00	✓
2	1 set	Top Garnish Clips	\$ <i>nn</i> 30.00	X
3	1 pc	Windscreen Sealant	\$ <i>nn</i> 50.00	405mm
4	1 set	Reverse Sensor	\$ <i>pu</i> 250.00	200mm
Parts Total :			\$ 3,084.84	
Labour				
1		To remove & rearrange electrical wirings, check lightings	\$ 80.00	201
2		To remove & replace upholstery, cushion seat & trim garnishes.	\$ 100.00	501
3		To remove, instal rear windscreen.	\$ 150.00	1201
4		To remove, transfer boot lid components	\$ 100.00	801
5		To remove, repair & replace damaged bodyparts, realign bodywork and where consistent to the accident.	\$ 600.00	451
6		Putty and respray painting on affected portions.	\$ 700.00	4001
7		To remove & renew reverse sensor	\$ 100.00	301
8		Rust proofing on affected portions.	\$ 100.00	301
Labour Total :			\$ 1,930.00	

Total Parts & Labour : \$ 5,014.84

for EM Solution Pte Ltd

LKK Auto Consumers Notice
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Supplementary

Date : 22nd August 2022

Cai Yi Service
Blk 120D Canberra Crescent
#10-407 Eastwave@Canberra
Singapore 754120

Veh No : SMQ 695B
Make/Model : Honda Vezel
Chassis No : RU11317608
Date of Acc : 18.08.22
TP Veh No : SKW 4967H

Qty	Description	Unit Price	Amount
	<u>Materials</u>		
1 pc	Rear Bumper Side LH	195.00	nd/c M \$ 235.20
1 pc	Rear Undersield		c M \$ 98.40
			\$ 333.60
		Less 20%	\$ 66.72
			\$ 266.88



for E M Solution Pte Ltd