

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE		Ref:	CS3/ASM22007966/Gqy3m4	
	8 SHENTON WAY SINGAPORE 0688		Date:	26/10/2022	
	ATTN: TEO KITTY			Code:	ASM
1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHA 7088B	Veh. Inspected		SLG 7176B
	Policy No.		Coverage (\$)		0.00
	Claim No.	S2M0499F	Excess (\$)		0.00
	Assign From	TEO KITTY	Assign Date		19/08/2022
2. Vehicle Particulars & Condition					
	Make & Model	HONDA SHUTTLE 1.5	c.c		1496
	Engine No.	HIDDEN	Year of Reg.		2016
	Chassis No.	GP71042096	Colour		BLACK
	Odometer	-	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195/55 R15	MAXXIS		6 mm
	L/H Front Tyre	195/55 R15	MAXXIS		6 mm
	R/H Rear Tyre	195/55 R15	MAXXIS		6 mm
	L/H Rear Tyre	195/55 R15	MAXXIS		6 mm
4. Description of Damages					
	THE VEHICLE SUS	BODY.			
5. General Information					
	Accident Date	18/08/2022	Inspect Date /	Time	22/08/2022 (05:00 PM)
	Survey held at T & S MOTOR SERVICE BLK 5035 ANG MO KIO INDUSTRIAL PARK 2 #01-357 . SINGAPORE 569538				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
5b.	Estimate Days of Repair				
JD.					

Report Ref No. CS3/ASM22007966/Gqy3m4

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.