



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2300364

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 17/01/2023
Reference CC3/CTI22007967/Vpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHA 7007K
Insured Veh. GBH 1615D
Claim No. SNM22D206005/C02
Policy No. DMCVSNW00113012100
Accident Date 24/07/2022
Inspection Date 25/07/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI22007967/Vpa3q2	
			Date: 17/01/2023	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBH 1615D	Veh. Inspected	SHA 7007K	
Policy No.	DMCVSNW00113012100	Coverage (\$)	0.00	
Claim No.	SNM22D206005/C02	Excess (\$)	0.00	
Assign From		Assign Date	25/07/2022	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI IONIQ	c.c	1580	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	KMHC851CVLU190894	Colour	BLUE	
Odometer	274013 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R19	WEST LAKE	5 mm	
L/H Front Tyre	195/65 R19	WEST LAKE	5 mm	
R/H Rear Tyre	195/65 R19	WEST LAKE	5 mm	
L/H Rear Tyre	195/65 R19	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/07/2022	Inspection Date	25/07/2022	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7007K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER RETAINER /RH	NECESSARY	41.40	41.40
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	588.80	-
1	FRONT FENDER RH SHIELD	SERVICEABLE	164.70	-
1	FRONT BUMPER COVER	DEFORMED	481.10	481.10
1	FRONT FENDER EMBLEM	NECESSARY	26.60	26.60
1	DAY LIGHT RH	SERVICEABLE	642.50	-
10	FRONT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	FRONT BUMPER MOULDING UPPER	SERVICEABLE	368.50	-
1	FRONT BUMPER GRILLE /RH	SCRATCHED	186.20	186.20
1	FRONT HEADLAMP ASSY /RH	CRACKED	2,110.30	2,110.30
1	FRONT WHEEL COVER RH	SERVICEABLE	346.40	-
	LESS 20% DISCOUNT		-995.70	-573.52
			3,982.80	2,294.08
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT FENDER RH .		750.00	350.00
	SPRAY PAINTING CHARGE.		600.00	250.00
	RESET WHEEL ALIGNMENT.		90.00	30.00
	CHECK WIRING.		60.00	30.00
	TUFF KOTE.		60.00	30.00
			1,560.00	690.00
	GRAND TOTAL		5,542.80	2,984.08
	RECOMMENDED COST OF REPAIRS			2,984.08

Report Ref No. CC3/CTI22007967/Vpa3q2

THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 7007K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 7007K

RE-INSPECTION

