



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDN 1801C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BUMPER LOWER SPOILER (ADDITIONAL)	BROKEN	1,702.00	1,702.00
	LESS 30% DISCOUNT		-510.60	-510.60
			1,191.40	1,191.40
	<b><u>NETT ITEMS</u></b>			
1	BUMPER FACE REAR FORESTER IL (N)	DEFORMED	555.00	555.00
1	BRKT CORNER R RH (N)	SERVICEABLE	18.50	-
1	BRKT CORNER R LH (N)	SERVICEABLE	18.50	-
1	BRKT SD R RH (N)	SERVICEABLE	14.80	-
1	BRKT SD R LH (N)	SERVICEABLE	14.80	-
1	COVER HOOK R (N)	SERVICEABLE	13.00	-
9	CLIP BMPR (N)	NECESSARY	21.60	21.60
2	CLIP (N)	NECESSARY	6.00	6.00
1	CARGO STEP PANEL S/S (N)	BENT	460.00	460.00
1	BEAM COMPL R EU (N) (ADDITIONAL)	BENT	296.00	296.00
1	COVER BMPR R (EXHAUST) (N) (ADDITIONAL)	SERVICEABLE	14.80	-
	LESS 20% DISCOUNT		-286.60	-267.72
			1,146.40	1,070.88
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			100.00	20.00
	<b><u>LABOUR</u></b>			
	REMOVE & REPLACE REAR BUMPER AND REAR BEAM.		1,130.00	560.00
	RESPRAY REAR BUMPER AND REAR BEAM.		1,000.00	420.00
	TO SUPPLY & INSTALL REVERSE SENSOR - 2 EYES.		300.00	300.00
	TO CONDUCT (REAR) LIGHTING TEST.		50.00	50.00
	FAULT DIAGNOSTIC (RESET) FIRST ITEM.		280.00	280.00
	REPAIR REAR FLOOR PANEL, REAR END PANEL (ADDITIONAL).		1,120.00	1,120.00
	RESPRAY REAR FLOOR PANEL, END PANEL, BUMPER BEAM (ADDITIONAL).		840.00	840.00

Report Ref No. CS/SMR22007972/Rny3m4



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & REFIX REAR BUMPER LOWER SPOILER (ADDITIONAL).		145.00	145.00
			4,865.00	3,715.00
GRAND TOTAL			7,302.80	5,997.28
RECOMMENDED COST OF REPAIRS				5,997.28

Report Ref No. CS/SMR22007972/Rny3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.