



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22007972/Rny3m4	
			Date: 15/11/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6039J	Veh. Inspected	SDN 1801C	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/08/22/2048	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	19/08/2022	
2. Vehicle Particulars & Condition				
Make & Model	SUBARU FORESTER 2.0I L S/R	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JF1SJ5KC5JG103627	Colour	GREY	
Odometer	073755 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/60 R17	YOKOHAMA	6 mm	
L/H Front Tyre	225/60 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	225/60 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	225/60 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/08/2022	Inspection Date	22/08/2022	
Survey held at	25 LENG KEE ROAD, SINGAPORE 159097			
Repairer	MOTOR IMAGE ENTERPRISES PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	