

PRPRISES PTE. LTD.
 0AD
 99097

AL LIST FOR ACCIDENT VEHICLE REGN NO SDN1801C

DAMAGED PARTS & PRICES

S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1	BUMPER FACE REAR FORESTER IL <i>de</i>	57704SG012	555.00	✓		
2	BRKT CORNER R RH <i>? Xsu</i>	57707SG060	18.50			
3	BRKT CORNER R LH <i>? Xsu</i>	57707SG070	18.50			
4	BRKT SD R RH <i>? Xsu</i>	57707SG080	14.80			
5	BRKT SD R LH <i>? Xsu</i>	57707SG090	14.80			
6	BEAM COMPL R EU (SUPP) <i>? Xsu 4</i>	57711SG0219P	296.00	✓		
7	COVER HOOK R <i>Xsu</i>	57731SG010NN	13.00			
8	COVER BMPR R (EXHAUST) (SUPP) <i>? Xsu</i>	57731SG060	14.80			
9	CLIP BMPR * 9 PCS <i>ne</i>	909140007	21.60	✓		
10	CLIP *2 PCS <i>ne</i>	909140062	6.00	✓		
11	CARGO STEP PANEL S/S <i>4</i>	E7710SG000	460.00	✓		
<i>*spoiler? bn suppl -1702</i>						
SUB TOTAL			1433.00	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			286.60	0.00	0.00	0.00
GRAND TOTAL			1146.40	0.00	0.00	0.00
OVERALL TOTAL			1146.40			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh
Singapore 319255
Tel: (65) 6703 8101/8102
Fax: (65) 6253 5535
www.motorimage.net
Co Reg No: 196720028

Insurance Co: SMRT

Survey Date: _____

SUPPLEMENTARY PARTS FOR VEHICLE REGISTRATION NO SDN 1801C

Surveyor: Rasul Star (LKK)

DESCRIPTION	31/8/22	PART NO	AMOUNT
1 Rear Bumper Beam	/	BT	
2 Bumper Lower Spoiler	/	BR	
3			
4			
5			
6			
7			
8			
9			
10			

LABOUR DESCRIPTION

AMOUNT

Repair Rear Floor Panel, Rear End Panel	\$1120-
Respray Rear Floor Panel, End Panel, Bumper Beam	\$840-
Remove & Refit Rear Bumper Lower Spoiler	\$145-

Supplementary Items

Approved By Surveyor

Name :

Insurance Company :

Date / Time :