



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel 6250 0088 Fax: 6250 5545

Email operation@tllauto.com.sg

GST No 201700521W UEN No 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SLN7284K

CLAIM TYPE : THIRD PARTY

TP INS. CO. : MSIG INSURANCE (SINGAPORE) PTE LTD

ACCIDENT DATE : 02/08/2022

TP VEH REG NO : SLN7284K

ESTIMATE

NO : QUOT202208-000030(00)

DATE : 19/08/2022

POLICY NO : 999995580

VEH REG NO : SMS2584P

MAKE/MODEL : MERCEDES BENZ CLA200
PROGRESSIVE (R18 LED SR)

CHASSIS NO : W1K1183872N080975

ENGINE NO : 28291480294637

REG. DATE : 2020

Not Authorised
Returning B&P
4 days

Estimate Repair Cost to Vehicle No : SMS2584P

Description	Quantity	Unit Price	Amount
NET PRICE			
1 Bonnet	1	2,040.00	2,040.00
2 Headlamp assy - LH	1	3,545.00	3,545.00
3 Front fender - LH	1	688.00	688.00
4 Front fender inner shield - LH	1	219.00	219.00
5 Front fender inner shield clips - LH	20	9.00	180.00
6 Front bumper	1	1,510.00	1,510.00
7 Front bumper side retainer - LH	1	38.00	38.00
8 Front bumper sensor seals	6	12.00	72.00
9 Front bumper clips	15	9.00	135.00
			8,427.00
Less 10%			842.70
			7,584.30
LABOUR			
10 To remove and refix front bumper sensor	1	100.00	100.00
11 To check and rectify wiring system	1	80.00	80.00
12 To panel beat & straighten LH front fender inner panel, LH front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	800.00	800.00
13 To putty and spray paint on affected areas	1	1,200.00	1,200.00
14 To reset and re-programme headlamp fault code	1	350.00	350.00
15 To apply rust-proofing on replaced and repaired panels	1	120.00	120.00
16 To computerise check wheel alignment	1	120.00	120.00
			2,770.00

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurer's Engineer

Acknowledged by Repairer

Signature:

Date:

TOTAL S\$ 10,354.30

ADD GST @ 7% 724.80

GRAND TOTAL S\$ 11,079.10

SINGAPORE DOLLAR ELEVEN THOUSAND SEVENTY NINE AND CENTS ONLY

TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE