

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SmK 8018K - 2018 Oct

BMW 520i 1998 CC

WBAJA12060WE60412.

TP Budget Direct.
Vern.

Rear Bumper	Delivered	1628	✓
Rear Bumper Clips	New	50	✓
Rear Bumper Side Holder RH.	HP new	116	x
Rear Bumper Sensor	HP new	250	x
Rear Bumper Sensor Holder	new x06.	28 x 6 = 168	✓
Taillamp RH.	HP new	692	x
Rear RH Fender	Repair	2016.	x
Rear RH Fender Inner Shield	HP new	215	x
Rear RH Fender Inner Shield Clips.	HP new	30	x
Rear Windscreen Moulding	HP new	210.	x
Rear Windscreen Sealant		60(SN)	x
Rear RH Wheel Rim.	at	1380. 700(SN)	
Rear RH Tyre.	HP new	300(SN)	x

SMK8018K.

Rees RH Shock Absorber	HP m	545.	+
Rees RH Lower Arm.	Bent	425.	✓
Rees RH Knuckle Arm.	HP m	1048.	x.
Rees RH Wheel Hub c/w Bearings	HP d	458.	✓
Rees RH Stay Arm.	Bent	314.	✓
Rees RH Control Arm.		309.	✓
			6429
			13,544
	3352	S.N: 700	
	3016.80		

Panel Beating		1200	500
Spray Painting.		1000	500
Wiring.	1480	50	30
To remove upholstery.		150	50
To remove rees windscreen.		180	x
To spray tuff coat		150	40.
To remove reverse sensor		100	60.
To perform wheel alignment		150	80
To dismantle rees undercarriage		350	220
		Total: 5196.8	
		H/S: 4.1K.	
		05 Days.	