



Repair Estimate

31	Front fender "HYBRID" emblem o/s	1	\$ 69.00	\$ 69.00
			<b>Subtotal</b>	<b>\$ 10,775.60</b>
			<b>List discount</b>	<b>20.00%</b>
			<b>Total</b>	<b>\$ 8,620.48</b>

Special nett items

No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front door inner trim board clips o/s	8	\$ 5.50	\$ 44.00
2	Front fender arch garnish clips o/s	8	\$ 5.50	\$ 44.00
3	Rocker panel sealant o/s	1	\$ 100.00	\$ 100.00
4	Front fender cowlings clips o/s	8	\$ 5.50	\$ 44.00
5	Front bumper clips	12	\$ 5.50	\$ 66.00
6	Front alloy wheel o/s	1	\$ 550.00	\$ 550.00
7	Front tyre o/s	1	\$ 280.00	\$ 280.00
8	Sundries	1	\$ 50.00	\$ 50.00
			<b>Total</b>	<b>\$ 1,178.00</b>

Labour

No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$ 1,400.00
2	To disconnect o/s front door wire harness and electrical component to facilitate repairs, reconnect and check functions of power windows.	0.25	\$ 50.00
3	To undercoat all affected portions after repair.	1	\$ 200.00
4	To remove and refit o/s front tyre & rim for replacement. To perform tyre balancing.	0.25	\$ 50.00
5	To remove and refit o/s front undercarriage for replacement of parts.	1	\$ 200.00
6	To conduct computerized 4 wheel alignment.	0.5	\$ 100.00
7	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00
<b>Total labour</b>			<b>\$ 3,200.00</b>

<b>Estimate Grand Total</b>	<b>\$ 12,998.48</b>
-----------------------------	---------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: