28.11.13, wef	2207979/4cy3
	GNMENT
ASSI	
From: Date:	Veh No: 65K/62J Yr Regn: 28/1/19
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Var / Lorry / Taxi / Prime Mover /
OD TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or (M/
To Inspect Vehicle No: 68/2/629	Make: Top for Dyna c.c 2982
at Workshop m/s Jin Aul.	Colour A/C: Insured / Std / NI / NA
of	Sp.Reading 144/28 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: JTFA T35. 190K21379
Claims No.	Gen. Cond Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: norder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil S/Rim / STD A/Rim or
	Tyre Size: F: 195- RIT
(Policy Condition)	R: 15-5-12 De/jun
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or mexmile
Bal. or Market Value:	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 42 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 3/3 mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 22/08/22
Lum Sym: / · /3 . / % 3 Val.: Yes or No	Survey held at
CA / REV) / REP. / 24 HRS C 665 R	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted: Vehicle: IN / OUT	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction Des 10k	The Gro / Chassis Hallic / Estay Structure allected due to Collision.
there heatly nos nic scrads	010
8	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
1) : Final Report Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee: Transportation:
2) Add Fee	
	: Interview (\$) Photos
Report Format:	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$: Weekend (\$
	TOTAL

Jin Auto Services Pte Ltd #01-410/412, 14 Defu Lane 10 539195

Insurer Reference: GBK162J Repairer Reference: GBK162J

Date calculated: 19/08/2022 11:50 AM

Full Report

Registration: GBK162J

Printed: 19/08/2022 11:50 AM

Summary Information

Claim

Location:

Singapore (SG)

Work Provider:

China Taiping Insurance (Singapore) Pte Ltd

Printed by:

Claim Reference:

JOUIS SEOW GBK162J

Currency: Date of Incident: SGD 18/08/22

Estimated Repair Time: Actual Repair Days:

Hire Car Start: Hire Car End:

Vehicle Details

Vehicle

Manufacturer: Model:

TOYOTA DYNA

Sub Model:

BASE MODEL

Model Sheet Number: Registration:

70 1C 01 GBK1623

VIN number:

JTFAT35Y90K213746

Odometer:

144128

Model Specs

STANDARD CAB

EUROPA MODEL

Not Authorist
Leck

Lexiss & SUD

The pho before gainly

22/08/27

5-Logs.

LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after snraw pointing

- To display damaged part(a) a mind resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All	
Jnderbody	



Tyres Condition

Tread (Left Middle), Tread (Left Outer), Tread (Left Inner), Tread (Right Inner), Tread (Right Outer), Tread (Right Tyre Brand

Condition

mm

mm

Middle), mm

Spare Tyre Brand

Tread (Spare), mm

Labour

Labour	Time Base 10 WU/h	Price = 42.	00 SGD/h
Code	Description Time base 10 Woyn	WU	Price SGD
NO NUMBER	RENEW ENGINE COVER R + R BADGE "DYNA" R + R FRONT BUMPER	60.0 2.0 4.0	252.00 8.40 16.80 12.60
520011) 751011 810051)	R + R RADIATOR GRILLE R + R L/HEADLAMP (RADIATOR GRILLE REMOVED)	3.0 1.0	4.20
810051)	DOES NOT INCLUDE: ADJUST HEADLAMP R + R R/HEADLAMP (RADIATOR GRILLE REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP	1.0	4.20
	ADJUST HEADLAMPS	3.0	12.60
810151A NO NUMBER NO NUMBER	RENEW FRONT NUMBER PLATE (REMOVED) R + R FRONT NUMBER PLATE	1.0 1.0 30.0	4.20 4.20 126.00
554011)	R + R WINDSCREEN INCLUDES: R + R SUN VISORS, UPPER FRONT PANEL AND A-PILLAR TRIMS	3.0	12.60
670051) 670051)	R + R LEFT FRONT DOOR R + R RIGHT FRONT DOOR	3.0	12.60

Code	Description		WU	Price SGD
743201) 883621) 550451) NO NUMBER 850161) NO NUMBER 441101 0934 1482	DETACH + REFIT HEADLINING R + R HEATING CPL R + R INSTRUMENT PANEL R + R INSTRUMENT PANEL CARRIER (REMOVED) R + R WIPER MOTOR (WIPER UNIT REMOVED) DRAIN + REFILL COOLANT R + R STEERING WHEEL R/A-PILLAR REINF REPAIR RIGHT FRONT DOOR REPAIR	30	4.0 21.0 9.0 2.0 7.0 3.0 4.0 45.0* 15.0*	16.80 88.20 37.80 8.40 29.40 12.60 16.80 189.00 63.00
	Labour Cost Panel / Mechanical Labour Total of Labour	Hrs 22.20	WU 222.0	932.40 932.40

Paint

Paint Work	Manufacturer	Time Bas	sis 10 WU/h
Code	Description - MF	W	J Price SGD
LE 0281 LE 0294 LE 0413 LE 0888 LI 1482 LS 0418 L 0934 NO NUMBER NO NUMBER	FRONT BUMPER NEW PART PAINT ST 1 R/F BUMPER BRACKET NEW PART PAINT ST 1 ENGINE FIREWALL NEW PART PAINT ST 1 R/END MOULDING NEW PART PAINT ST 1 RIGHT FRONT DOOR REPAIR PAINT ST III OUTER ENG FIREWALL REPAIR PAINT ST IV R/A-PILLAR REINF INNER- PAINT STG II PREPARE FOR PAINTING PAINT PREPARATION FOR PLASTIC PARTS (COMPOSITE WORK)	11.0 5.0 27.0 6.0 15.0 12.0 4.0 13.0 3.0	21.00 113.40 25.20 63.00 50.40 16.80 54.60
	Total Paint	Hrs Wt 9.60 96.0	

Spare Parts

Spare Parts			prices as at	2015-06	5-01/01
Code	Description	Part Number	Part Source		rice SGD
0257 0294 0410 0413 0418 0431 0433 0572 0888 1410	FRONT NUMBER PLATE R/F BUMPER BRACKET GRILLE ENGINE FIREWALL OUTER ENG FIREWALL BADGE BADGE MODEL RIGHT HEADLAMP ASSY R/END MOULDING WINDSCREEN SEAL WINDSCREEN BOND KIT	KNPL3 52011 37034 53111 37891 55700 37440 55078 37120 75315 37080 75311 37160 81130 37120 53813 37100A0 56121 25040 PZ49I 00C1131	Original	Sert one one cone cone cone cone	25.00 110.00× 240.00 450.00 160.00 35.00 30.00 350.00 120.00 0.00 0.00
f: OEM Parts n: Non-OEM Parts u: Used parts	Savings Subtotal			1	0.00 .,520.00

Total 1,520.00

Final Calculation		
	SGD	SGD
Parts Total Parts	1,520.00	1,520.00
Labour Time Base 10 WU/h Total 222.0 WU X 42.00 SGD/h Total of Labour	932.40	932.40
Paint Work Time Base 10 WU/h Labour Cost 96.0 WU X 42.00 SGD/h Total Paint Including Material	403.20	403.20
Repair Cost Excludes GST		2,855.60
GST (+7.00%) Repair Cost Included GST		199.89 3,055.49

Comments

* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	665R
Vehicle Details	
Vehicle No.:	GBK162J
Vehicle to be Exported:	No so
Intended Deregistration Date:	22 Aug 2022
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	1KD2860551
Chassis No.:	JTFAT35Y90K213746
Maximum Power Output:	-
Open Market Value:	\$27,082.00
Original Registration Date:	25 Nov 2019
First Registration Date:	25 Nov 2019
Transfer Count:	0
Actual ARF Paid:	\$1,355.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Nov 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$26,001.00
COE Rebate Amount:	\$18,865.00
Total Rebate Amount:	\$18,865.00

The information contained herein is correct as at 22 Aug 2022

ОК

Login Sign up

New Cars

Used Cars

Rental Cars

Ways of Selling

Model

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



Post an Advertisement Sell it yourself! Advertise it at just \$68 until it's SOLD! Rare Unique Underused Muscle Car - Chrysler 300C

Mileage 36500, High PARF Rebate. Immaculate Condition (9.9/10) Acadent Free Direct Owner StarAd

YONG LEE SENG MOTOR PTE LTD

Sort by Date Posted

20

results/page

10 vehicles

Post an Ad

Toyota Dyna

Price

Any

Any Category

Advanced Search

Search

Status

Search Selection

Toyota Dyna

Advertiser Login

Any

Depreciation

2019

Reg Date

Any

Eng Cap

Available

Toyota Dyna 150 3.0M

\$72,800

\$11,210 /yr

18-Feb-2019

2,982 cc

Truck

Veh Type

Available

PREMIUM AD

Fuel Type: Diesel

Well maintained by previous owner. Rare high railing unit. 1 owner only. Known for its reliability. Wear and tear all done up. Buy with a...

Car (S) Pte Ltd

Posted: 22-Aug-2022

Toyota Dyna 150 3.0M

\$78,800

\$11,840 /vr

18-Apr-2019

2,982 cc

Truck

Available

PREMIUM AD

Fuel Type: Diesel

Most Popular 10Ft Lorry In The Market. New Paintwork Done. Original Upholstery. Engine, Gearbox Smooth. Super Low Mileage. No Rep...

ABS Bus Pte Ltd

Posted: 22-Aug-2022

Toyota Dyna 150 3.0M

\$77,800

\$11,630 /yr

30-Apr-2019

2.982 cc

Truck

Available

Fuel Type: Diesel

Low mileage 10 feet G plate lorry, come with full canopy and checker plate. New paintwork and loan can be arrange. Call for viewing!

ABWIN (1994) Pte Ltd

Posted: 22-Aug-2022



Toyota Dyna 150 3.0M

\$79,800

\$11,000 /yr

21-Nov-2019

2.982 cc

68,677 km Truck Available

Fuel Type: Diesel

1 owner only! Low mileage done! Still in great condition! No sign wear and tear so far! Comparable to brand new! Affordable quantum f...

Posted: 19-Aug-2022



Suzuki introduces the new Across

Suzuki introduces the new Across SUV, the first model supplied from Toyota under the Toyota and Suzuki collaboration.

Read this article



Toyota Dyna 150 3.0M

\$78,800

\$11,200 /yr

04-Sep-2019

2.982 cc

47,971 km

Truck

Available

PREMIUM AD

Fuel Type: Diesel

Agent unit! Agent serviced! Cheap and low depreciation! Exclusive engine and gearbox coverage! Fresh paintwork! Original upholstery!...

Car (S) Pte Ltd

Posted: 19-Aug-2022

Toyota Dyna 150 3.0M

\$76,800

\$11,980 /yr

18-Jan-2019

2,982 cc

38,530 km

Truck

Available

Fuel Type: Diesel

Tailgate Toyota Dyna. Best assist for loading and unloading of heavy Bucky items. Easy to operate by manual or wireless remote Control.

Posted: 18-Aug-2022

