

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIS22007982/RPA3Q2**Date:** 20/09/2022REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SPMF1000000516		
Claimant Vehicle No :	SFZ8388X	Insured Vehicle No :	PC3446Y		
Date of Loss:	18/08/2022	Nature of Claim:	TP	Claim No:	NGTAISCL2021-00008KC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFZ8388X		
Make & Model:	VOLKSWAGEN GOLF, 1.4 A7 TSI 5G13GZ SR HID (A)	Engine No:	CZC165388
Reg. Date:	24/10/2017 (Man. Year: 2016)	Chassis No:	WVWZZZAUZHW127782
Colour:	Grey	Odometer:	68084 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40Z R18	Rear Tyre Size:	225/40Z R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,736.33	1,862.71	873.62	31.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,960.00	1,880.00	3,080.00	62.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,696.33	3,742.71	3,953.62	51.37
+ GST 7.00/7.00% (S\$)	538.74	261.99	276.75	51.37
Nett Amount (S\$)	8,235.07	4,004.70	4,230.37	51.37
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)		321.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,333.15		
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	22/08/2022		
Date Inspected:	22/08/2022	Inspected At:	Volkswagen Group Singapore Pte Ltd 247 ALEXANDRA ROAD Singapore 159934
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Sep 2022)

Parts: 144 VOLKSWAGEN GOLF 1.4 A7 TSI 5G13GZ SR HID (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SFZ8388X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Deformed	1,244.46 FS	*1,244.46 FS
2	1		*REAR DIFFUSOR SATIN BLACK	Scratched	314.29 FS	*314.29 FS
3	2		*SENSOR BRACKET	Necessary	28.94 FS	*28.94 FS
4	1		*SENSOR BRACKET	Necessary	14.47 FS	*14.47 FS
5	1		*SENSOR BRACKET	Necessary	14.47 FS	*14.47 FS
6	1		*2K-PLASTIC ADHESIVE	Necessary	77.35 FS	*77.35 FS
7	1		*BONDING AGENT FOR PLASTIC	Necessary	61.97 FS	*61.97 FS
8	1		*BUMPER REINFORCEMENT	Not Necessary	659.15 FS	*- FS
9	1		*ATTACHMENT STRIP BUMPER CTR BRACKET	Not Necessary	63.67 FS	*- FS
10	1		*GUIDE PIECE LHR BUMPER BRACKET (UPPER)	Not Necessary	37.70 FS	*- FS
11	1		*GUIDE PIECE RHR BUMPER BRACKET (UPPER)	Not Necessary	37.70 FS	*- FS
12	1		*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	Not Necessary	37.70 FS	*- FS
13	1		*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	Not Necessary	37.70 FS	*- FS
14	1		*RIVET (4 PCS)	Necessary	4.75 FS	*4.75 FS
15	1		*NUMBER PLATE	Bent	80.00 FS	*80.00 FS
16	1		*SET SENSOR BRACKETS PRI	Necessary	22.01 FS	*22.01 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **2,736.33** **1,862.71**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	0.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	2,160.00	720.00
4	SPRAY PAINT	New	2,040.00	680.00
Gross Labour Cost (\$\$)			4,960.00	1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >