



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22007985/Kvy3q2 Date: 07/09/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLN 1129R	Veh. Inspected	GBG 4529E	
Policy No.	P10704912R00	Coverage (\$)	0.00	
Claim No.	C10016973/JM	Excess (\$)	0.00	
Assign From	SALIZAWATI HAIZAR	Assign Date	19/08/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTFAT35YX0K208488	Colour	SILVER	
Odometer	132562 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	YOKOHAMA	3 mm	
L/H Front Tyre	195 R15X8	YOKOHAMA	3 mm	
R/H Rear Tyre	155 R12X8 (D)	YOKOHAMA	5/5 mm	
L/H Rear Tyre	155 R12X8 (D)	YOKOHAMA	5/5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/08/2022	Inspection Date	22/08/2022	
Survey held at	GLOBAL AUTO SPECIALIST PTE LTD BLK 176 SIN MING DRIVE #04-14 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	