

ASS. REC. BY:

REF:

A15 / 22 00 7988 / Ke

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

I.B.I. %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: S110 9980 XYr Regn: 01 / 21Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) / Prime Mover /

Truck / Trailer or

Make: Toy Prius

c.c

1798Colour M.P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading 128807

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU103093673Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD / A/Rim orTyre Size: F: Pailun 195/65R15R: DonBS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 5 mmR/Bal. 2 mmL/Bal. 5 mmL/Bal. 2 mmD.O.A. 7/5/22D.O.A. 22/8/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
olsbody

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

23/8 @ 2255.33 Cahr

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) S + RS. \$

) Extras

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Not Notified
Recovery B4 point

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9980X

82255.33

AAD2205-036

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

22 AUG 2022

SHD9980X

JTDKB3FU103093673

200303878K

TOYOTA

PRIUS GEN 4

07/05/2022

XE853U/ Allianz

29/01/2021

PART	LIST
1 PANEL SUB-ASSY, FRONT DOOR, RH	\$ 1,300.70 X
1 FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$ 193.50 X
1 HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$ 390.60 X
1 TAPE, BLACK OUT, NO.2 FRT RH	\$ 43.50 X
1 TAPE, BLACK OUT, NO.1 FRT RH	\$ 13.30 X
1 TAPE, BLACK OUT, NO.3 FRT RH	\$ 26.30 X
1 PANEL SUB-ASSY, REAR DOOR, RH	\$ 1,294.90 ✓
1 WEATHERSTRIP, REAR DOOR OPENING TRIM, RH	\$ 293.00 X
1 FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$ 193.50 X
1 HANDLE ASSY, REAR DOOR OUTSIDE, RH	\$ 97.40 X
1 MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH	\$ 926.00 X
1 REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$ 206.70 X
1 TAPE, BLACK OUT, NO.2 REAR RH	\$ 34.90 ✓
1 TAPE, BLACK OUT, NO.3 REAR RH	\$ 15.40 ✓
1 TAPE, BLACK OUT, NO.1 REAR RH	\$ 21.90 ✓
1 HINGE ASSY, REAR DOOR, LOWER RH	\$ 87.10 X
1 HINGE ASSY, REAR DOOR, UPPER RH	\$ 98.90 X
1 MIRROR ASSY, OUTER REAR VIEW, RH	\$ 1436.6 X
1 PANEL SUB-ASSY, QUARTER, RH	\$ 871.50 X
1 LINER, REAR WHEEL HOUSE, RH	\$ 139.80 X
1 MOULDING ASSY, BODY ROCKER PANEL, RH	\$ 594.80 X
1 COVER, REAR BUMPER	\$ 485.60 X
TOTAL	\$ 8,765.90
25%	\$ 2,191.48
	\$ 6,574.43

Trans-cab Auto Services Pte Ltd**AAD2205-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9980X**Special Nett**

1	REAR FENDER LINER CLIP	\$	na	65.00	X
1	REAR BUMPER RETAINER CLIP	\$	na	75.00	X
1	DOOR STICKER TRANSCAB	\$	na	100.00	60sm
1	DOOR STICKER TEL. NO	\$	na	100.00	60sm
1	DOOR TRIM CLIP	\$	na	75.00	X
1	DOOR WEATHERSTRIP CLIP	\$	na	80.00	X
TOTAL		\$		495.00	

TOTAL PARTS \$ 7,069.43**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	300
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00 X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	400
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	na	380.00 X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	600
To reinstall rear bumper parking sensor.	\$	na	170.00 X
To transfer of tire, rim and on wheel balancing.	\$	na	170.00 X
To Check Electrical Lighting Concerned.	\$	170.00	200

Trans-cab Auto Services Pte Ltd

AAD2205-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9980X

To check steering geometry and computer wheel alignment \$ *nn* 220.00 XTo remove and refit of rear fender fittings, attachment and
perform water seepage test.\$ *nn* 170.00 X**TOTAL** \$ **5,100.00****Over All Total** \$ **12,169.43**

(PART-BY-PART) Repair Days

*20 Days**3 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by:

Signature:

Date: