## COMPORT DELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

Updated 11 Feb 2020

DATE:

10.06.22

MODEL:

Hyundai Ioniq (Front)

VEHICLE NO.: SHC1079G

INSURANCE: NTUC

MVA: JUMANI

PART NO.	DESCRIPTION	D.O.A	10.06.22		
	FRT BUMPER	QTY	UNIT PRICE		TNUC
	FRT FENDER RH			\$	481.10
	FRT FENDER RH - EMBLEM			\$	588.80
	HEADLAMP ASSY RH			\$	26.60 N
	FRT BUMPER CTR MOULDING			\$	2,110.30
	FRT WHEEL CAP RH			\$	368.50
	FRT BUMPER SIDE BRACKET RH			\$	346.40
	FRT BUMPER CLIPS			\$	41.40 M
		10		\$	22.00
	SUB TOTAL				
	LESS 20%				3,985.10
	DISCOUNTED TOTAL			\$	797.02
				\$	3,188.08
	SUB TOTAL				
	Labour Charge				
	Panel Beating			•	70
	Spray Painting Charge		1	\$	800.00 50
	Wiring Charge		1	\$ \$	
	Tuff Kote		1	s \$	50.00 30 50.00 30
	Advertisement logo - Fender			\$ \$	100.00 M
					100.00 / 1
	TOTAL LABOUR			\$ 1	,600.00
	ESTIMATE TOTAL			\$ 4	,788.08
	prepared after the vehicle is surveyed by a motor Surve				

Thwau 82238769 10/6/22 17/0 L/S 3dayswp

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: