

FALCON AIR AUTO SERVICES PTE LTD

HSIAO Tony

Tel No. :

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building 78 Shenton Way #07-16
079120

Attention : Motor Claim Department

Contact : 6419 3000

Estimate : ES708452

Date : 20/08/2022
Vehicle Num. : SLF 1506C
Make/Model : HONDA JAZZ
Chassis/Eng# :
Accident Date : 20/08/2022
Claim No. :
Reference :
Policy No. :

4/5 \$4100

not Authorized
see
accident
22/08/22
5 days
2/5 \$4100
the whole After 4/5

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1 PC	TAILGATE	910.50	970.00
2.	1 PC	TAILGATE LOCK	145.50	224.00
3.	1 PC	TAILGATE JAZZ EMBLEM	16.00	42.00
4.	1 PC	TAILGATE GLASS MOULDING	88.00	162.00
5.	1 PC	TAILGATE TRIM BOARD		252.00
6.	1 SET	REVERSE SENSOR (4PC)		300.00
7.	1 PC	TAILGATE WEATHERSTRIP		145.00
8.	1 PC	TAILGATE INNER HANDLE		67.00
9.	1 PC	REAR BUMPER	492.50	928.00
10.	2 PCS	REAR BUMPER SIDE RETAINER	25.00	50.00
11.	1 PC	REAR END PANEL	397.90	490.00
12.	1 PC	REAR END PANEL GARNISH		125.00
13.	1 PC	REAR END PANEL SEALANT		100.00
14.	1 PC	TAILGATE BUZZER	64.50	135.00
15.	2 PCS	REAR FENDER INNER TRIM	295.00	590.00
List TotalS\$:				4,580.00
20.00% Discount S\$:				916.00
				3,664.00

SPECIAL NETT ITEMS :				
1.	1 PC	TAILGATE SEALANT	50	100.00

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building 78 Shenton Way #07-16
079120

Attention : Motor Claim Department

Contact : 6419 3000

Estimate : ES708452

Date : 20/08/2022
Vehicle Num. : SLF 1506C
Make/Model : HONDA JAZZ
Chassis/Eng# :
Accident Date : 20/08/2022
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

2.	1 PC	TAILGATE GLASS SEALANT		40.00
3.	1 PC	TAILGATE GLASS INNER SEAL		80.00
4.	1 PC	TAILGATE TRIM BOARD CLIPS		40.00
5.	1 PC	REAR NUMBER PLATE		45.00
6.	1 PC	REAR BUMPER CLIP		40.00
7.	1 PC	REAR END PANEL GARNISH CLIP		50.00
8.	1 PC	REAR FENDER INNER TRIM CLIPS		80.00

Special Nett Total S\$:

475.00

LABOUR :

TRANSFER TAILGATE GLASS
TRANSFER TAILGATE MECHANISM
RESPRAY ANTI RUST
APPLY BODY SEALANT TO CAR JOINTS
INSTALL REVERSE SENSOR
TO CHECK LIGHT SYSTEM AND WIRING
TO INSTALL REVERSE CAMERA
TO REMOVE/REFIX INNER TRIMS, GARNISH AND ETC TO
FACILITATE REPAIRS
WATER TEST TO CHECK FOR LEAKAGE
TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, CUT/REWELD
REAR END PANEL, REPLACEMENT OF PARTS AND ALIGN THE SAME
TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA

150.00
120.00
150.00
150.00
100.00
50.00
150.00
150.00
50.00
900.00
1,000.00

Labour Total S\$:

2,970.00

E. & O.E.

Total S\$:

7,109.00

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-3574-90
202
2889.92
250
2090
5199.92