



Exceptional Journeys

Surveyor : STEVE LKK
Claim : TP CHINA TAIPING
DOA : 16.08.2022
Emailed : 18.10.2022, 4.35pm
Date survey : 13.09.2022

VEHICLE NO : SNA 4999 X
MODEL : MIT OUTLANDER 2.0
WIP : 26347

Material	:	\$	<u>4,436.00</u>
Labour	:	\$	<u>4,450.00</u>
Sub-Total	:	\$	<u>8,886.00</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>8,886.00</u>
GST 7%	:	\$	<u>622.02</u>
Grand Total	:	\$	<u>9,508.02</u>
Finalise By/Date	:	LOI /	<u>18/10/2022</u>

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☒ REPAIR TOOK 6 WORKING DAYS + 2 Days (1) Weekends
+ 1 Days (1) Waiting surveyor
TOTAL DAYS REPAIR TOOK = 9

☒ TP claim GBC 2175 B

☒ Claim GIA / LTA fee \$2.00

☒ Claim Loss of ☐ Use / ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Mr Muhammad Shadiq Bin Aziz Blk 799 Yishun Ring Road #06-3418 Singapore 760799 Contact No Mobile: 91871714 13/09/2022	Cust No/Name	/Mr Muhammad Shadiq Bin Aziz
	Reg No/Reg Date	SNA4999X / 04/01/2019
	Date In/Mileage	13/09/2022/ 63046
	Chassis/Package	GF7W0600414 /#
	Engine No	4J11AB7858
	Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)
	Colour/Trim	P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00040	Cash	13/10/2022/ 12:10	TLE	260 / AiTing	26347			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE TAILGATE, REAR BUMPER, REPAIR LH REAR FENDER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 1280.00
E PNT98000 RESPRAY ON TAILGATE, REAR BUMPER, LH REAR FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 1650.00
E PNT88000 REMOVE & REINSTALL TAILGATE COMPONENTS TO FACILITATE REPAIR								✓ 280.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM								✓ 100.00
A 10028901 CONDUCT DIAGNOSTIC CHECK ON USING MUT TESTER AND CLEAR TROUBLE CODE								✓ 280.00
E PNT88000 REMOVE & REINSTALL REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST								✓ 320.00
M SUNDRY SUPPLY REAR WINDSCREEN GLASS SEALANT								✓ 80.00
E PNT88000 REMOVE & REINSTALL REVERSE SENSOR TO FACILITATE REPAIR								✓ 80.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS								✓ 40.00
M SUNDRY SUPPLY BODY PANEL SEALANT								✓ 40.00
M SUNDRY SUPPLY C&C BADGE								✓ 50.00
M SUNDRY SUNDRIES								✓ 30.00
S SPECIALISTJOB SUPPLY ONE SET OF REVERSE SENSOR								✓ 220.00
M SUNDRY SUPPLY LAMP ASSY, TAIL, LH → was quoted under parts.								✓ 613.00
X FACE,RR BUMPER					1.00	✓ 1158.00	00.00	1158.00
X EXTENSION,RR BUMPER					1.00	✓ 499.00	00.00	499.00



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Mr Muhammad Shadiq Bin Aziz Blk 799 Yishun Ring Road #06-3418 Singapore 760799 Contact No Mobile: 91871714 13/09/2022	Cust No/Name	/Mr Muhammad Shadiq Bin Aziz
	Reg No/Reg Date	SNA4999X / 04/01/2019
	Date In/Mileage	13/09/2022/ 63046
	Chassis/Package	GF7W0600414 /#
	Engine No	4J11AB7858
	Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)
	Colour/Trim	P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CTP00040	Cash	13/10/2022/ 12:10	TLE	260 / AiTing	26347		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
X	BRKT,R/BMPR FACE SIDE,LH			1.00	✓ 27.00	00.00	27.00
X	MOULDING,RR BUMPER,LH			1.00	✓ 128.00	00.00	128.00
X	MOULDING,RR WHEEL ARCH,LH			1.00	✓ 162.00	00.00	162.00
X	DAM,TAILGATE SIDE			2.00	✓ 33.00	00.00	66.00
X	DAM,TAILGATE,UPR			1.00	✓ 13.00	00.00	13.00
X	FASTENER,WINDSHIELD			4.00	✓ 8.00	00.00	32.00
X	STOPPER,WINDSHIELD GLASS			2.00	✓ 4.00	00.00	8.00
X	DAM,TAILGATE,LWR			1.00	✓ 24.00	00.00	24.00
X	MARK,OUTLANDER			1.00	✓ 115.00	00.00	115.00
X	REFLECTOR,TAIL LAMP,LH			1.00	✓ 101.00	00.00	101.00
X	BUZZER,KEYLESS OPERATIO,RR			1.00	✓ 92.00	00.00	92.00
X	CLIP,ENG ROOM COVER			10.00	2.00	00.00	20.00
X	PANEL ASSY,TAILGATE			1.00	✓ 1378.00	00.00	1378.00
Z	TEXT						
	TP CLAIM CHINA TAIPING						
	DOA : 16.08.22						
	SURVEYOR STEVE 13.09.22						
	REPAIR 06 DAYS						

Pro Formula

Supp

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	3,823.00	Nett	8,886.00
Labour	3,990.00	7% GST on	622.02
Standard Menu	0.00		
Specialist Job	220.00	Total Payable	9,508.02
Diagnostics Job	0.00		
Sundry/Others	853.00		
Total(w/o GST)	8,886.00		

This is not an official tax invoice.
This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO. : CHINA TAIPING

Supplementary Parts For Registration No.: SNA 4999 X

<u>Materials</u>		<u>Cost (\$)</u>	
1	Buzzer, keyless operatio, RR	92.00	✓ BR
2	Clips (x10)	20.00	✓ NEC
Total		112.00	
7% GST		7.84	
Grand total		<u>\$ 119.84</u>	

Thank You.

Yours faithfully,
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

LOI AI TING
SENIOR OFFICER-ADMIN
MITSUBISHI SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240