



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: ANG YVONNE			Ref: CS/ASM22008019/Uqy3e2 Date: 31/08/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHA 1229B	Veh. Inspected	SNB 7325R	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S2M049CR	Excess (\$)	0.00	
Assign From	ANG YVONNE	Assign Date	22/08/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA HARRIER HYBRID (A)	c.c	2487	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	AXUH800026324	Colour	BROWN	
Odometer	39433 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/65 R17	BRIDGESTONE	7 mm	
L/H Front Tyre	225/65 R17	BRIDGESTONE	7 mm	
R/H Rear Tyre	225/65 R17	BRIDGESTONE	7 mm	
L/H Rear Tyre	225/65 R17	BRIDGESTONE	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	20/08/2022	Inspection Date	23/08/2022	
Survey held at	PROFI AUTOMOTIVE BLK 10 KAKI BUKIT ROAD 2 #01-05 FIRST EAST CENTRE SINGAPORE 417868			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	