



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z
 Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 5737986
 HP: 98888885

Estimation

Date: 22/8/2022
 Vehicle: SNB7611P
 Make / Model: TOYOTA PRIUS
 Chassis: BUDGET DIRECT

No.	Description	Unit	Unit Price	Amount	
1	TAILGATE DETECTOR ? X NN	1	\$ 321.00	\$ 321.00	X
2	REAR BUMPER → ✓ DD	1	\$ 658.00	\$ 658.00	525 ✓
4	REAR BUMPER REINFORCEMENT ? X NN	1	\$ 350.50	\$ 350.50	X
5	REAR BUMPER BRACKET X NN	2	\$ 114.00	\$ 228.00	X
6	REAR BUMPER LIP ✓ ll	1	\$ 728.90	\$ 728.90	417 ✓
7	REAR END PANEL X NN	1	\$ 660.20	\$ 660.20	X
				\$ 2,946.60	
			Less 20%	\$ 589.32	942 -25%
			Total	\$ 2,357.28	706.50
	S/Nett items:				
1	REAR BUMPER CLIPS ? ✓ NEC	1	\$ 80.00	\$ 80.00	30 ✓
2	REAR REVERSE SENSOR ? ✓ shorted	1	\$ 250.00	\$ 250.00	200 ✓
3	REAR END PANEL SEALANT X NN	1	\$ 60.00	\$ 60.00	
				\$ 390.00	230
	Labour to:				
1	TO CHECK REAR ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00	X NN
2	TO REMOVE AND RENEW REVERSE SENSOR	1	\$ 150.00	\$ 150.00	40
4	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00	X NN
5	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 400.00	\$ 400.00	200
6	PANEL BEATING ON AFFECTED AREAS	1	\$ 400.00	\$ 400.00	200
				\$ 1,230.00	440
			Parts Replacement Amount	\$ 2,747.28	
			Total Amount for Labour	\$ 1,230.00	
			Total Amount	\$ 3,977.28	

2 Days -
 L/S
 After repair photo
 Eric Ong
 22/8/22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: