



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z
 Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 5737986
 HP: 98888885

Estimation

Date: 22/8/2022
 Vehicle: SNB7611P
 Make / Model: TOYOTA PRIUS
 Chassis: BUDGET DIRECT

No.	Description	Unit	Unit Price	Amount
1	TAILGATE DETECTOR ?	1	\$ 321.00	\$ 321.00
2	REAR BUMPER ?	1	\$ 658.00	\$ 658.00
4	REAR BUMPER REINFORCEMENT ?	1	\$ 350.50	\$ 350.50
5	REAR BUMPER BRACKET X NP	2	\$ 114.00	\$ 228.00
6	REAR BUMPER LIP <i>all</i>	1	\$ 728.90	\$ 728.90
7	REAR END PANEL X NP	1	\$ 660.20	\$ 660.20
				\$ 2,946.60
			Less 20%	\$ 589.32
			Total	\$ 2,357.28
	S/Nett items:			
1	REAR BUMPER CLIPS ?	1	\$ 80.00	\$ 80.00
2	REAR REVERSE SENSOR ?	1	\$ 250.00	\$ 250.00
3	REAR END PANEL SEALANT X NP	1	\$ 60.00	\$ 60.00
				\$ 390.00
	Labour to:			
1	TO CHECK REAR ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
2	TO REMOVE AND RENEW REVERSE SENSOR	1	\$ 150.00	\$ 150.00
4	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00
5	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 400.00	\$ 400.00
6	PANEL BEATING ON AFFECTED AREAS	1	\$ 400.00	\$ 400.00
				\$ 1,230.00
			Parts Replacement Amount	\$ 2,747.28
			Total Amount for Labour	\$ 1,230.00
			Total Amount	\$ 3,977.28

2 Days -
 4/5
 After repair photo
 Eric Ong
 22/8/22

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
 Signature:
 Date: