



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

ATTN : ACCOUNTS DEPT

FAX :

*NOT Notified
Repairing By Repair
4 days
11/12/22 2300h*

YOUR REF NO : SML5766Z
CLAIM TYPE : THIRD PARTY
TP INS. CO. : ECICS LIMITED
ACCIDENT DATE : 30/07/2022
TP VEH REG NO : SML5766Z

ESTIMATE

NO : QUOT202208-000040(00)
DATE : 22/08/2022
POLICY NO : 999995730
VEH REG NO : SMX8421K
MAKE/MODEL : MERCEDES BENZ A180
SALOON PROGRESSIVE
CHASSIS NO : W1K1771842J283950
ENGINE NO : 28291480519953
REG. DATE : 2021

Estimate Repair Cost to Vehicle No : SMX8421K

Description	Quantity	Unit Price	Amount
NET PRICE		S\$	S\$
1 Front door - LH <i>1750</i>	1	1,750.00	1,750.00 <i>By</i>
2 Front door weatherstrip - LH <i>325</i>	1	328.00	328.00 <i>in</i>
3 Front door trimboard rivets - LH	20	12.00	240.00 <i>in</i>
4 Rear door - LH	1	2,048.00	2,048.00 <i>R</i>
5 Rear door weatherstrip - LH	1	328.00	328.00 <i>in</i>
6 Rear door trimboard rivets - LH	20	12.00	240.00 <i>in</i>
			4,934.00
		Less 10%	493.40
			4,440.60
LABOUR			
7 To transfer LH front & rear door interior mechanism and glass to new door	1	300.00	300.00 <i>sol</i>
8 To check and rectify wiring system	1	80.00	80.00 <i>2d</i>
9 To panel beat and straighten LH centre pillar, LH rocker panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00 <i>400d</i>
10 To putty and spray paint on affected areas	1	1,200.00	1,200.00 <i>440d</i>
11 To apply rust-proofing on replaced and repaired panels	1	160.00	160.00 <i>in</i>
			2,740.00
TOTAL			S\$ 7,180.60
ADD GST @ 7%			502.64
GRAND TOTAL			S\$ 7,683.24

SINGAPORE DOLLAR SEVEN THOUSAND SIX HUNDRED EIGHTY-THREE AND CENTS TWENTY-FOUR ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed

FOR TONG LUCK AUTO PTE LTD

Acknowledged by Repairer