

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 9 1993103/9 7825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

TP Chin
Xiao Am

22 August 2022

QUOTATION FOR ACCIDENT REPAIR OF SLR3186R HONDA SHUTTLE

THIRD PARTY INSURER: CHINA TAIPING

S/No.	Parts List	Qty	Amount (\$)
1.	Front grille <i>could</i>	1	\$ 235.00 ✓
2.	Front grille top chrome <i>new</i>	1	\$ 240.00 +
3.	Front grille logo emblem <i>new</i>	1	\$ 68.00 ✓
4.	Front grille logo base <i>new</i>	1	\$ 96.00 +
5.	Front bumper <i>could</i>	1	\$ 1180.00 ✓ 985
6.	Front bumper towing cover <i>new</i>	1	\$ 38.00 +
7.	Front bumper side retainer L/R <i>new</i>	2	38.00 \$ 76.00 +
8.	Front bumper reinforcement beam <i>Bent</i>	1	\$ 380.00 ✓
9.	Front headlamp L/R <i>RTA could</i>	2	1680 \$ 3360.00 1680
10.	Front headlamp lower bracket L/R <i>RTA could</i>	2	68.00 \$ 136.00 68.
Subtotal before discount			\$ 5809.00
Discount 20%			\$ 1161.80
Subtotal 1			\$ 4647.20

S/NETT	Parts List	Qty	Amount (\$)
1.	Front parking sensor <i>new</i>	1	\$ 350.00 +
2.	Front bumper clip <i>new</i>	1	\$ 30.00 ✓
3.	Front no plate (Acrylic) <i>new</i>	1	\$ 150.00 +
S/Nett Total			\$ 530.00

LABOUR

To check wirings.

To straighten, repair, realign on rear affected area and replace damaged parts

To spray painting on affected area

Total Labour Cost

\$ 80.00 30
\$ 500.00 300
\$ 500.00 200
\$ 1080.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Admin by
L/S 23/08/22
03 Days
Total: 3292.80
A/S: 2.6K