



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22008044/Any3e2	
			Date: 17/10/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKR 3091S	Veh. Inspected	SND 1926K	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2202866/GPL	Excess (\$)	0.00	
Assign From	MELVIN YE	Assign Date	22/08/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	MR2BE3BE500017034	Colour	SILVER	
Odometer	9867 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MICHELIN	6 mm	
L/H Front Tyre	205/65 R16	MICHELIN	6 mm	
R/H Rear Tyre	205/65 R16	MICHELIN	6 mm	
L/H Rear Tyre	205/65 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/08/2022	Inspection Date	23/08/2022	
Survey held at	LEANG AUTOMOTIVE BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	