

FINAL COST OF REPAIR

(To be completed for only one type of item)

| | | | |
|--|--------------------------------------|--------------------|------------------------------|
| To: _____ <div style="text-align: center; margin: 5px 0;">Unit S4</div> _____ <div style="text-align: center; margin: 5px 0;">Unit</div> | From: | Ref | BB75/(9AMB)/92FMD/CCSW/22/03 |
| _____ 9AMB/92FMD/CLEMENTI CSW Base/LEO Area Office | | | |
| Description of Item: | TRK,CARGO:5 TONS,M.A.N. 16.284 LAERC | SAF 1222: | 602H/(3TPT)/D/014/22 |
| Part/Reg No: MID21576 | Original Value: \$147,048 | Date: | 16-Aug-22 |
| Quantity: 01 | CE/Non CE: Non CE | SAF 1204/SAF 1351: | 8202796086 |
| Description of Damages and Costs of Repairs: | | Date: | 16.08.2022 |
| | | Workshop Job No: | 8202796086 |
| | | Date: | 16.08.2022 |
| <u>MATERIAL COST</u> (Each line item to indicate amount before GST) | | | |
| DESCRIPTION | Qty | Unit Price | Total Price |
| FENDER,VEHICULAR:PLASTIC,BACK POS (NSN:123618130) | 1 | \$ 737.30 | \$737.30 |
| | | | \$0.00 |
| <u>LABOUR COST</u> (Each line item to indicate amount before GST) | | | |
| | Man Hour | Rate | \$28.00 |
| Left hand front fender rear cracked and chipped off | 2 | | \$56.00 |
| Remove & refit left hand front fender rear | | | |
| <u>Assessment Fee</u> (Each line item to indicate amount before GST) | | | |
| DF-Equip charged under basic | | | \$0.00 |
| <u>General Services</u> (Each line item to indicate amount before GST) | | | |
| Tow Svc Wheeled | | | \$0.00 |
| Base/LEO Area Office's Assessment of Damages | | | |
| Labour Charges @ \$28.00 per hour x 2 | hrs = | | \$56.00 |
| Total Cost of Parts / Materials Used | = | | \$737.30 |
| Sub-contractor | = | | |
| Assessment Fee | = | | \$0.00 |
| Towing Service | = | | \$0.00 |
| Grand Total (Before GST Amount) | | | \$793.30 |
| Total Repair Time: | 2 | | |
| _____ [Digitally Signed in PDF by MAO] | | | |

*Delete whichever is not applicable