



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 7349J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	TAILLAMP RH	BROKEN	375.00	320.00
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	869.00	-
1	REAR CORNER PANEL RH	SERVICEABLE	142.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,585.00	-
	LESS 25% DISCOUNT		-742.75	-80.00
			2,228.25	240.00
<b>LABOUR</b>				
	STRAIGHTEN & PANEL BEAT ACCIDENT AREA. INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL RH & REAR FENDER RH.		800.00	200.00
	RESPRAY REAR FENDER RH, TAILLAMP PANEL RH, REAR CORNER PANEL.		700.00	200.00
			1,500.00	400.00
<b>GRAND TOTAL</b>			<b>3,728.25</b>	<b>640.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>640.00</b>

Report Ref No. CS/FCI22008051/Kvy3m4

**MARKET VALUE: \$27,000.00(EST)-LTA REIMBURSEMENT VALUE: \$7,312.00=NETT VALUE: \$19,688.00**

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**