

Vehicle Damage Assessment Report for [SMD2610B]

Estimate Created: 23/09/2022 06:39 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 03/03/2023 14:29 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company		Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Mercedes-Benz	Model	CLA
Engine Type			
License Plate Number	SMD2610B	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK: CONCLUDED THE COST OF REPAIR AT \$5,700.00 WITH 4 WORKING DAYS	Insurlogic 5 (03/03/2023 14:28)
- Check parts price	Insurlogic 1 (23/09/2022 11:28)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
BOOTLID WEATHERSTRIP		1	266.00	-10.00 %	239.40
TAILLAMPS		1	805.00	-10.00 %	724.50
TAILLAMP LOWER BRACKETS		1	105.00	-10.00 %	94.50
REAR BUMPER		1	1615.00	-10.00 %	1,453.50
REAR BUMPER LOWER SPORT		1	1200.00	-10.00 %	1,080.00
SET REAR BUMPER CLIPS		1	60.00	-10.00 %	54.00
REAR BUMPER BEAM		1	681.00	-10.00 %	612.90
REAR END PANEL		1	1205.00	-10.00 %	1,084.50
REAR END PANEL SEALANT		1	50.00	-10.00 %	45.00
REAR BUMPER REVERSE SENSOR (N/S)		1	215.00	-10.00 %	193.50

Parts Subtotal 5,581.80

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
TO CHECK WIRING	RnR	20.00	0.00 %	20.00
TO DISMANTLE & REPLACED REAR REVERSE SENSOR	RnR	50.00	0.00 %	50.00
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	RnR	80.00	0.00 %	80.00
TO SPRAY RUST PROOFING	RnR	40.00	0.00 %	40.00
LABOUR FOR PANEL BEATING & REPLACED PARTS	RnR	600.00	0.00 %	600.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
TO PUTTY & SPRAY PAINTING	Full spray	800.00	0.00 %	800.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 790.00

Paint Labor Subtotal 800.00

Labor Subtotal 1,590.00

Summary

Repair Cost	7,171.80
Discount(20 %)	(1,434.36)
	5,737.44
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	5,737.44