

Date: 22/08/2022
 Vehicle No: SLX4569G
 Model: TOYOTA WISH 1.8 CVT
 Chassis: JTDGG20W00J009222-2017
 Reg.Year: 2018

Not Authorized
11 Pay @ 1250/-
Running After Rain
3 days

Third Party Insurer: AIG
 Third Party Veh No: SKA1200Y
 Date of Accident: 19/08/2022
 Estimator: TING AN
 Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		<i>Bu</i> \$645.00
2	REAR BUMPER SIDE BRACKET RH	1		<i>in</i> \$95.00
3	REAR BUMPER REFLECTOR RH	1		<i>in</i> \$70.00
4	REAR END PANEL	1		REPAIR
5	REAR TAILGATE	1		REPAIR
SUB TOTAL				\$810.00
LESS 25%				-\$202.50
PARTS TOTAL				\$607.50

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		<i>in</i> \$50.00
2	REAR BUMPER REVERSE SENSOR	1		<i>shot</i> \$300.00
S/N TOTAL				\$350.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC. \$700.00 *400*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR TAILGATE, REAR END PANEL & ETC. \$700.00 *400*

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC. \$100.00 *50*

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. \$80.00 *10*

LABOUR TOTAL \$1,580.00

TING AN TOTAL \$2,537.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

