

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22008056/RCE2**Date:** 31/01/2023**REFERENCE**

Insured/Claimant:	PANG YOKE CHEE	Policy No:	2100470586-06	
Date of Loss:	18/08/2022	Nature of Claim:	OD	Claim No: 9967756078SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD9374Z	Engine No:	CVN013726
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Chassis No:	WAUZZZF41GA106230
Reg. Date:	30/06/2016 (Man. Year: 2016)	Odometer:	143729 km
Colour:	Grey		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$82,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35Z R19	Rear Tyre Size:	245/35Z R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,619.00	13,421.36	8,197.64	37.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,692.00	7,802.00	7,890.00	50.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	37,311.00	21,223.36	16,087.64	43.12
+ GST 8.00/8.00% (S\$)	2,984.88	1,697.87	1,287.01	43.12
Nett Amount (S\$)	40,295.88	22,921.23	17,374.65	43.12

INSPECTION

Date of Assignment:	23/08/2022		
Date Inspected:	22/08/2022	Inspected At:	24 Benoi Sector Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	9.0 days		

Adjuster: MOHD RASUL**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR	Bent	3,431.00 FS	*2,744.80 FS
2	1		*FRONT OUTER DOOR SEAL - LH	Necessary	229.00 FS	*182.80 FS
3	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
4	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
5	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
6	1		*FRONT DOOR CATCH - LH	Not Necessary	116.00 FS	*- FS
7	1		*FRONT DOOR SEAL - INNER	Not Necessary	229.00 FS	*- FS
8	1		*FRONT DOOR HANDLE HOUSING - LH	Cracked	9.00 FS	*6.88 FS
9	1		*FRONT DOOR HANDLE TRANSPARENT COVER - LH	Missing	7.00 FS	*5.36 FS
10	1		*FRONT DOOR HANDLE SENSOR - LH	Scratched	255.00 FS	*203.60 FS
11	1		*FRONT EXTERIOR DOOR HANDLE	Cracked	47.00 FS	*37.12 FS
12	2		*FRONT DOOR HANDLE UNDERLAY - LH FRONT / REAR	Necessary	8.00 FS	*6.40 FS
13	1		*FRONT DOOR MOUNTING BAR - RH	Broken	183.00 FS	*146.40 FS
14	1		*FRONT WING MIRROR MOUNTING - LH	Scratched	1,201.00 FS	*960.80 FS
15	1		*FRONT WING MIRROR CAP - LH	Not Necessary	308.00 FS	*- FS
16	1		*FRONT WING MIRROR GLASS - LH	Not Necessary	1,298.00 FS	*- FS
17	1		*FRONT WINDOW REGULATOR	Bent	305.00 FS	*244.00 FS
18	1		*FRONT WINDOW REGULATOR MOTOR - LH	Not Necessary	346.00 FS	*- FS
19	1		*FRONT DOOR CONTROL UNIT	Not Necessary	840.00 FS	*- FS
20	1		*FRONT WINDOW SLOT SEAL TRIM STRIP	Bent	344.00 FS	*274.80 FS
21	1		*FRONT WINDOW GUIDE	Not Necessary	501.00 FS	*- FS
22	1		*FRONT DOOR LOCK - RH	Bent	796.00 FS	*636.40 FS
23	1		*FRONT DOOR STRIKER	Not Necessary	77.00 FS	*- FS
24	1		*FRONT DOOR TRIM - LH	Cracked	2,278.00 FS	*1,822.40 FS
25	1		*REAR DOOR	Bent	3,431.00 FS	*2,744.80 FS
26	1		*REAR OUTER DOOR SEAL - LH	Necessary	229.00 FS	*182.80 FS
27	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
28	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
29	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
30	1		*REAR DOOR SEALING STRIP	Not Necessary	19.00 FS	*- FS
31	1		*REAR DOOR CATCH - LH	Not Necessary	134.00 FS	*- FS
32	1		*REAR DOOR UPPER HINGE - LH	Not Necessary	49.00 FS	*- FS
33	1		*REAR DOOR UPPER HINGE HALVES - LH	Bent	51.00 FS	*40.16 FS
34	1		*REAR DOOR LOWER HINGE HALVES - LH	Bent	53.00 FS	*41.68 FS
35	1		*REAR DOOR LOWER HINGE HALVES - LH	Not Necessary	53.00 FS	*- FS
36	1		*REAR LOWER PANEL SIDE MEMBER - LH	Bent	2,339.00 FS	*1,871.20 FS
37	1		*AIRBAG / CHILDS SEAT PICTOGRAM STICKER	Necessary	27.00 FS	*21.28 FS
38	1		*FRONT DOOR SILL TRIM STRIP	Necessary	133.00 FS	*106.00 FS
39	1		*REAR WINDOW SLOT SEAL TRIM STRIP	Not Necessary	410.00 FS	*- FS
40	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
41	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
42	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
43	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
44	1		*SUNDRIES	Necessary	400.00 FS	*15.12 FS
45	1		*FRONT DOOR HANDLE EXTERIOR COVER - RH	Missing	98.00 FS	*77.92 FS
46	1		*PERIPHERAL LIGHT - LH FRONT (Supplementary)	Broken	81.00 FS	*64.24 FS
47	1		*FRONT DOOR B-PILLAR TRIM - LH (Supplementary)	Crushed	256.00 FS	*204.40 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 21,619.00 13,421.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, ABCD PILLAR TRIMS, SILL TRIMS, FLOOR CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS. DISENGAGE LHS SEAT BELT AND HEAD AIRBAG	New	1,800.00	1,800.00
2	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER	New	800.00	0.00
3	TO PUT UP THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR	New	2,400.00	0.00
4	TO DISMANTLE AND RENEW LHS FRONT DOOR AND LHS REAR DOOR. TO CUT OUT AND WELD LHS SILL PANEL WITH LHS B-PILLAR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,900.00	2,500.00
5	TO RESPRAY LHS FRONT DOOR, LHS REAR DOOR, LHS WING MIRROR COVER, DOOR HANDLE, HINGES, LHS SILL PANEL, LHS B-PILLAR AND DOOR ENTRANCES	New	4,900.00	2,750.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
7	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	700.00	560.00
Gross Labour Cost (\$)			15,692.00	7,802.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >