

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0717/2022/EQ
DATE : 20-Aug-22
WIP : 38117

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/8/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Rasul

9 12 days exclude 1 Sunday

Johnny Boo 2 Dec 22

OWNER'S NAME : MR. PANG YOKE CHEE
ADDRESS : 259 YISHUN ST 22
#07-73
SINGAPORE 760259
TELEPHONE : HP +65 94777263
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100470586-06
VEHICLE NO : **SLD 9374 Z**
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S-TRONIC
MODEL YEAR : 30/6/2016
ENGINE NO : CVN 013726
CHASSIS NO : WAUZZZF41GA106230
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Aug-22
PLACE OF ACCIDENT : SERANGOON NORTH AVE 1 NEAR BLK 119

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLD 9374 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	700.00	\$	560.00
2	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, ABCD PILLAR TRIMS, SILL TRIMS, FLOOR CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS. DISENGAGE LHS SEAT BELT AND HEAD AIRBAG.	S/N \$	1,800.00	\$	1,800.00
3	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER.	S/N \$	800.00		
4	TO PUT UP THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR.	S/N \$	2,400.00		
5	TO DISMANTLE AND RENEW LHS FRONT DOOR AND LHS REAR DOOR. TO CUT OUT AND WELD LHS SILL PANEL WITH LHS B-PILLAR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,900.00	\$	2,500.00
TOTAL LABOUR CHARGES		:	\$ 10,600.00	\$	4,860.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLD 9374 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	<i>C/F</i>		\$ 4,860.00
6	TO RESPRAY LHS FRONT DOOR, LHS REAR DOOR, LHS WING MIRROR COVER, DOOR HANDLE, HINGES , LHS SILL PANEL, LHS B-PILLAR AND DOOR ENTRANCES.	\$ 4,900.00	\$ 2,750.00
7	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 15,692.00	\$ 7,802.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLD 9374 Z

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT		REMARKS
1	FRONT DOOR	1	\$	3,431.00	\$ 2,744.80
2	FRONT OUTER DOOR SEAL - LH	1	\$	229.00	\$ 182.80
3	BONDING AGENT	1	\$	51.00	
4	CLEANING SOLUTION	1	\$	74.00	
5	APPLICATOR	1	\$	9.00	
6	FRONT DOOR CATCH - LH	1	\$	116.00	
7	FRONT DOOR SEAL - INNER	1	\$	229.00	
8	FRONT DOOR HANDLE EXTERIOR COVER - RH	1	\$	98.00	\$ 77.92
9	FRONT DOOR HANDLE HOUSING - LH	1	\$	9.00	\$ 6.88
10	FRONT DOOR HANDLE TRANSPARENT COVER - LH	1	\$	7.00	\$ 5.36
11	FRONT DOOR HANDLE SENSOR - LH	1	\$	255.00	\$ 203.60
12	FRONT EXTERIOR DOOR HANDLE	1	\$	47.00	\$ 37.12
13	FRONT DOOR HANDLE UNDERLAY - LH FRONT / REAR	2	\$	8.00	\$ 6.40
14	FRONT DOOR MOUNTING BAR - RH	1	\$	183.00	\$ 146.40
15	FRONT WING MIRROR MOUNTING - LH	1	\$	1,201.00	\$ 960.80
16	FRONT WING MIRROR CAP - LH	1	\$	308.00	
17	FRONT WING MIRROR GLASS - LH	1	\$	1,298.00	
18	FRONT WINDOW REGULATOR	1	\$	305.00	\$ 244.00
19	FRONT WINDOW REGULATOR MOTOR - LH	1	\$	346.00	
20	FRONT DOOR CONTROL UNIT	1	\$	840.00	
SUB TOTAL SPARE PARTS		:	\$	9,044.00	\$ 4,616.08

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLD 9374 Z

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		C/F		\$	4,616.08
21	FRONT WINDOW SLOT SEAL TRIM STRIP	1	\$ 344.00	\$	274.80
22	FRONT WINDOW GUIDE	1	\$ 501.00		
23	FRONT DOOR LOCK - RH	1	\$ 796.00	\$	636.40
24	FRONT DOOR STRIKER	1	\$ 77.00		
25	FRONT DOOR TRIM - LH	1	\$ 2,278.00	\$	1,822.40
26	REAR DOOR	1	\$ 3,431.00	\$	2,744.80
27	REAR OUTER DOOR SEAL - LH	1	\$ 229.00	\$	182.80
28	BONDING AGENT	1	\$ 51.00		
29	CLEANING SOLUTION	1	\$ 74.00		
30	APPLICATOR	1	\$ 9.00		
31	REAR DOOR SEALING STRIP	1	\$ 19.00		
32	REAR DOOR CATCH - LH	1	\$ 134.00		
33	REAR DOOR UPPER HINGE - LH	1	\$ 49.00		
34	REAR DOOR UPPER HINGE HALVES - LH	1	\$ 51.00	\$	40.16
35	REAR DOOR LOWER HINGE HALVES - LH	1	\$ 53.00	\$	41.68
36	REAR DOOR LOWER HINGE HALVES - LH	1	\$ 53.00		
37	REAR LOWER PANEL SIDE MEMBER - LH	1	\$ 2,339.00	\$	1,871.20
38	AIRBAG / CHILD'S SEAT PICTOGRAM STICKER	1	\$ 27.00	\$	21.28
39	REAR DOOR SILL TRIM STRIP	1	\$ 133.00	\$	106.00
40	REAR WINDOW SLOT SEAL TRIM STRIP	1	\$ 410.00		
SUB TOTAL SPARE PARTS		:	\$ 11,058.00	\$	12,357.60

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLD 9374 Z

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		C/F		\$	12,357.60
41	ACRYLIC SEALANT	S/N	\$ 180.00	\$	180.00
42	CAVITY WAX	S/N	\$ 140.00	\$	140.00
43	METAL FILLER POWDER	S/N	\$ 280.00	\$	280.00
44	STONE CHIP	S/N	\$ 180.00	\$	180.00
45	Add parts		\$ 337.00	\$	268.64
56	SUNDRIES		\$ 400.00	\$	15.12
TOTAL SPARE PARTS		:	\$ 21,619.00	\$	13,421.36
TOTAL LABOUR CHARGES		:	\$ 15,692.00	\$	7,802.00
GRAND TOTAL		:	\$ 37,311.00	\$	21,223.36

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-29/11/22



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0717/2022/EQ 30-Aug-22 CHANG 1 of 1 SLD 9374 Z AUDI A4 SEDAN 1.4 TFSI	
Quantity	Description		Unit Price	Amount
<u>Parts</u>				
1	PERIPHERAL LIGHT - LH FRONT	1	\$ 81.00	\$ 64.24
2	FRONT DOOR B-PILLAR TRIM - LH	1	\$ 256.00	\$ 204.40
GRAND TOTAL			\$ 337.00	\$ 268.64

For Premium Automobiles Pte Ltd

Authorised Signature