

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD	R	Ref:	CS3/ASM22008064/Gqy3e2	
	8 SHENTON WAY SINGAPORE 0688	D	Date:	26/09/2022		
	ATTN: HO WINNIE		C	Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHC 8522Y	Veh. Inspected		SMZ 6177T	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S2M049GQ	Excess (\$)		0.00	
	Assign From	HO WINNIE	Assign Date		23/08/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	HONDA SHUTTLE 1.5G	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2021	
	Chassis No.	GK82102205	Colour		BLACK	
	Odometer	50748 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	185/60 R15	TOYO		6 mm	
	L/H Front Tyre	185/60 R15	TOYO		6 mm	
	R/H Rear Tyre	185/60 R15	TOYO		6 mm	
	L/H Rear Tyre	185/60 R15	TOYO		6 mm	
4.		Description of Damages				
	THE VEHICLE SUS	HICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5.	General Information					
	Accident Date	20/08/2022	Inspect Date / Ti	me	29/08/2022 (05:30 PM)	
	Survey held at	BLK 3014 UBI ROAD 1 #01-282				
	Repairer	AH LUCK MOTOR & TRADING				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					

Report Ref No. CS3/ASM22008064/Gqy3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.