

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22008071/TQY3Q2**Date:** 01/11/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MM000629
Claimant Vehicle No :	SH6125S	Insured Vehicle No :	XD5967Y
Date of Loss:	23/08/2022	Nature of Claim:	TP
		Claim No:	M2204505

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH6125S	Engine No:	G4LEJU132618
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVKU121995
Reg. Date:	11/12/2018 (Man. Year: 2018)	Odometer:	660291 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,700.20	1,413.64	3,286.56	69.92
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,500.00	880.00	620.00	41.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,211.20	2,304.64	3,906.56	62.90
Approved Total (Overridden) (S\$)		1,850.00		
(S\$)	6,211.20	1,850.00	4,361.20	70.22
+ GST 7.00/7.00% (S\$)	434.78	129.50	305.28	70.21
Nett Amount (S\$)	6,645.98	1,979.50	4,666.48	70.22

INSPECTION

Date of Assignment:	23/08/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	23/08/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Nov 2022)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SH6125S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER ASSY	Deformed	481.10 FL	*481.10 FL
2	10		*FRT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*FRT BUMPER CENTRE MOULDING	Cut	368.00 FL	*368.00 FL
4	1		*FRT BUMPER SIDE BRACKET RH	Deformed	35.00 FL	*35.00 FL
5	1		*FRT FOG LAMP RH	Cut	642.50 FL	*642.50 FL
6	1		*FRT FOG LAMP GRILLE RH	Cut	93.45 FL	*93.45 FL
7	1		*FRT RADIATOR GRILLE ASSY	Not Necessary	1,409.10 FL	*- FL
8	1		*FRT RH FENDER	Repair	588.80 FL	*- FL
9	1		*HEADLAMP ASSY RH	Not Necessary	2,110.30 FL	*- FL
10	1		*ADVERTISEMENT LOGO - FENDER	Cut	100.00 F	*100.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,850.25	1,742.05
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,150.05	328.41
Total Parts (\$\$)	4,700.20	1,413.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	350.00
2	SPRAYPAINT	New	600.00	500.00
3	CHECK WIRING	New	50.00	30.00
4	TUFF KOTE	New	50.00	0.00
Gross Labour Cost (\$\$)			1,500.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >