

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd
20 McCallum Street
#09-01 Tokio Marine Centre
Singapore 069046

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tang Hock Lye Ben

Date: 27 Oct 2022

Preliminary Advice

Insured : XD5967Y
Vehicle No
TP Vehicle : SH6125S
No
Accident Date : 23/08/2022
Make : HYUNDAI IONIQ HYBRID
Assignment Date : 23/08/2022
Date of : 23/08/2022
Inspection Est. Duration of : 2
Repair
Inspection At : COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)
59 LOYANG DRIVE
SINGAPORE 508969

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,211.20
Revised Amount	:S\$	2,304.64
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,304.64

Lump Sum Repair	:S\$	1,850.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.