

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 24 Mar 2023

## Preliminary Advice

Insured Vehicle No : SLR6547M  
TP Vehicle No : SMM853H  
Make : HYUNDAI AD AVANTE  
Date of Inspection : 23/08/2022  
Inspection At : 2020 SPRAY PAINTING PTE LTD  
8 KAKI BUKIT AVENUE 4,  
#03-19, PREMIER @ KAKI BUKIT, SINGAPORE 415875

Accident Date : 21/08/2022  
Assignment Date : 23/08/2022  
Est. Duration of Repair : 7

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,600.72
Revised Amount	:S\$	9,112.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	9,112.80
Lump Sum Repair	:S\$	7,300.00

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

- The vehicle is economical for repair
- The vehicle is not economical for repair
- Part-by-Part repair
- Lump Sum repair

- The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advice amount (Revised) stated are subject to consistency check, part prices and labour cost.