

2020 SPRAY PAINTING PTE LTD
8 KAKI BUKI AVENUE 4
#03-19 PREMIER@KAKI BUKIT
SINGAPORE 415875

Vehicle No. SMM853H

HYUNDAI AVANTE

KMHD841CMKU879035

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
PARTS (LIST ITEMS)				
1	REAR BUMPER <i>2 behind</i>		474.90	✓
2	REAR BUMPER SIDE HOLDER RH <i>new</i>		35.80	+
3	REAR RH FENDER <i>Repis</i>		1854.90	+
4	REAR RH FENDER INNER SHIELD <i>new</i>		165.90	+
5	RERA WINDSCREEN MOULDING <i>new</i>		159.40	+
6	REAR RH DOOR <i>Dented.</i>		1846.90	✓
7	REAR RH DOOR LOCK <i>new</i>		247.80	+
8	REAR RH DOOR WEATHERSTRIPE <i>new</i>		135.80	+
9	REAR RH DOOR INNER TRIM BOARD <i>new</i>		645.60	✓
10	REAR RH DOOR GLASS REGULATOR GEAR <i>Dented</i>		185.60	✓
11	REAR RH DOOR GLASS REGULATOR MOTOR <i>new</i>		365.20	+
12	REAR DOOR HINGE @47.50 <i>new</i>		95.00	+
13	ROCKER PANEL <i>Repis</i>		1545.00	+
14	FRONT RH DOOR <i>Dented</i>		1785.60	✓
15	FRONT RH DOOR LOCK <i>new</i>		268.10	+
16	FRONT RH DOOR WEATHERSTRIPE <i>new</i>		131.70	+
17	FRONT RH DOOR INNER TRIM BOARD <i>new</i>		664.10	✓
18	FRONT RH DOOR REGULATOR GEAR <i>Dented</i>		198.10	✓
19	FRONT RH DOOR GLASS REGULATOR MOTOR <i>new</i>		378.20	+
20	FRONT DOOR HINGE @47.50 <i>new</i>		95.00	+
21	FRONT RH FENDER <i>Dented.</i>		1227.70	✓
22	FRONT RH FENDER INNER SHIELD <i>new</i>		171.40	+
23	FRONT RH FENDER MUDFLAP <i>new</i>		65.10	+
24	REAR AXLE <i>new</i>		1388.70	+
25	REAR RH WHEEL HUB C/W BEARING <i>new</i>		456.30	+
26	REAR RH SHOCK ABSORBER <i>new</i>		263.10	+
		7028.50		
		5622.80		
		less	20%	20%
			14850.90	
			2970.18	
			11880.72	
SPECIAL NETT ITEMS				
1	REAR BUMPER CLIPS <i>new</i>		30.00	✓
2	REAR FENDER INNER SHIELD <i>new</i>		30.00	+
3	REAR FENDER SEALANT <i>new</i>		60.00	+
4	REAR DOOR INNER TRIM BOARD CLIPS <i>new</i>		30.00	✓
5	REAR DOOR SURROUND MOULDING <i>new</i>		150.00	80
6	REAR DOOR BLACK TAPE <i>new</i>		60.00	✓
7	ROCKER PANEL SEALANT <i>new</i>		60.00	+
8	FRONT DOOR INNER TRIM BOARD CLIPS <i>new</i>		30.00	✓
9	FRONT DOOR SURROUND MOULDING <i>new</i>		150.00	80
10	FRONT DOOR BLACK TAPE <i>new</i>		60.00	✓
11	FRONT FENDER INNER SHIELD CLIPS <i>new</i>		30.00	+

12	REAR WHEEL RIM <i>cut</i>		800.00 450.
		Total Parts	1490.00

820

2020 SPRAY PAINTING PTE LTD
 8 KAKI BUKI AVENUE 4
 #03-19 PREMIER@KAKI BUKIT
 SINGAPORE 415875

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	OUR ASSESSMENT (\$)
	LABOUR		
1	PANEL BEATING	1800.00 1000	
2	SPRAY PAINTING	1600.00 1200	
3	WIRING	100.00 30	
4	TO APPLY TUFF COAT	150.00 60	
5	TO REMOVE UPHOLSTERY	150.00 40	
6	TO REMOVE REVERSE SENSOR	100.00 50	
7	TO TRANSFER FRONT & REAR DOOR FITTINGS	300.00 160	
8	TO REMOVE FRONT & REAR SEAT	250.00 X	
9	TO DISMANTLE REAR UNDERCARRIAGE	380.00 X	
10	TO PERFORM WHEEL ALIGNMENT	150.00 80	2670.
11	TO REMOVE REVERSE SENSOR	100.00 50	
12	TO REMOVE REAR EXHAUST PIPE	150.00 X	
	Labour Total :	5230.00	
	TOTAL (PARTS & LABOUR):	18600.72	

total: 9112.80

r/s: 7.3K.

07 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: