



VAG Singapore Pte Ltd
48 Toh Guan Road East
#05-136, Enterprise Hub
Singapore 606586

Repair Estimate

Tel: 6267 9916
Fax: 6267 9313
www.avantage.sg

Date: 19-Aug-2022

Vehicle Num: SJK286R

Make/Model: Volkswagen Sportvan L4 Highline AM14H

Chassis No: WVVZZZAUZGWS72511

S/N	PARTS	QTY	PRICE	TOTAL
1	RH Rear Fender, Outer <i>st/</i>	1	\$ 1,362.62	\$ 1,362.62
2	RH Rear Fender, Inner <i>repair</i>	1	\$ 810.98	\$ 810.98
3	RH Rear Fender Shield <i>turn</i>	1	\$ 135.68	\$ 135.68
4	RH Guide Piece, Fender <i>9 cm</i>	1	\$ 32.40	\$ 32.40
5	Rear Bumper <i>turn</i>	1	\$ 945.98	\$ 945.98
6	RH Guide Piece, Tail-light <i>? X m</i>	1	\$ 36.89	\$ 36.89
7	RH Parking Sensor, Outer <i>? X m</i>	1	\$ 140.40	\$ 140.40
8	RH Rear Wheel/Rim <i>cut</i>	1	\$ 930.68	\$ 930.68
<i>Resul</i> <i>4p 90010068</i> <i>5 days</i> <i>L/S</i> <i>23/08/22 @ 1545</i> <i>Resumy after repair</i>				
TOTAL PARTS			\$	4,395.63
Less 10%			\$	439.56
TOTAL AMOUNT			\$	3,956.07
MISCELLANEOUS ITEM				
1	Sunderies		\$ 50.00	\$ 20 50.00
2	Tuff Kote		\$ 50.00	\$ 30 50.00
3	RH Rear Tyre		\$ 276.00	\$ 11X 276.00
LABOUR				
1	Remove and refit/Cut and weld RH Rear Fender out, inner, Shield, Guide Pieces, Sensor, Rear Bumper and other associate components.		\$ 960.00	\$ 600 750 960.00
2	Surface preparation, spray paint and polish RH Rear Fender outer, Inner, Sensor, Rear Bumper and other affected areas.		\$ 750.00	\$ 400 500 750.00
3	Remove, refit and balance RH Rear Wheel/Rim.		\$ 25.00	\$ 25.00
4	Check and adjust Wheel alignment.		\$ 100.00	\$ 60 100.00
5	Diagnostic check and erase fault codes after the repair.		\$ 80.00	\$ 50 80.00
<i>2229.01</i> <i>600.00</i> <i>50.00</i> <i>L/S - \$3,450</i> <i>1385.00</i> <i>4264.01</i> <i>20%</i>			TOTAL	\$ 6,247.07
<i>3411.20</i>			GST 7%	\$ 437.29
GRAND TOTAL			\$	6,684.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: