



友尼摩多公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

JMONC30F2C0203262

TP MSIG.

LKK

Veron

DATE: 13/10/2022 OUR REF: UAPL1552
REPAIR ESTIMATE TO THE MAZDA MX 5 no: SKJ4759K
REAR ITEM:-

- 1 BOOT ASSY
- 1 BOOT LOCK
- 1 BOOT WEATHERSTRIP
- 1 REAR END PANEL
- 1 BUMPER ASSY
- 2 BUMPER SIDE RETAINER
- 2 BUMPER BRACKET
- 1 BUMPER REINFORCEMENT
- 2 BUMPER GROMMET
- 2 BUMPER SIDE CLIPS
- 10 BUMPER CLIPS
- 1 PANEL LINING
- 1 EXHAUST PIPE ASSY
- 2 EXHAUST MOUNTING
- 1 FENDER AIR GRILLE

\$	1,288.80	X
\$	131.50	X
\$	119.60	X
\$	458.00	X
\$	118.50	X
\$	164.80	X
\$	86.00	X
\$	615.40	X
\$	12.00	X
\$	47.80	20.
\$	50.00	30.
\$	212.30	X
\$	810.30	X
\$	70.00	X
\$	55.50	X
\$	5,187.00	
\$	1,037.40	
\$	4,149.60	

LESS 20%.....

SPECIAL NETT:-

- 1 REAR NUMBER PLATE
- 1 REAR EXHAUST CHROME PIPE
- 1 REAR REVERSE SENSOR

\$	50.00	X
\$	120.00	X
\$	280.00	250

250

LABOUR CHARGES:-

- TO DISM/RENEW REAR REVERSE SENSOR
- TO DISM/REWIRE DAMAGED PORTION
- TO SPRAY UNDERCOATING IN REPAIR
- TO DISM/REFIX REAR ROOF LINING, PILLAR LINING.
- TO PANEL BEAT DAMAGED PORTION, CHASSIS FRAME AND RENEW PARTS

\$	100.00	50
\$	120.00	30
\$	120.00	X
\$	150.00	X

630

TO PUTTY AND RESPRAY DAMAGED PORTION

\$	800.00	300
\$	800.00	250
\$	120.00	X
\$	6,809.60	

Total 200844

L/S: 16K
02ay

1.6K

the Repairer of the following:

TO DISM/RENEW EXHAUST BOX

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: